


# Crater report 169 of RG2

#### **General information**



**ID**: 169

Study area: RG2 Swirl: off-swirl

Morphology: Bowl-shaped

Estimate state of degradation : C

Mean Diameter: 60m ± 4.0m

Mean depht:  $1.5m \pm 0.2m$ 

**d/D ratio** :  $0.025 \pm 0.004$ 

**Circularity index**: 0.92

Mean slope: 3.28°

Mean value of TRI on the rim crest: 0.07

**Geometric center coordinates :** (3658238.967343969, 235394.84267165526)

**Coordinates of the crater's lowest point :** (3658239.000001101, 235391.0000000695)

### Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	4.67	0.57
10°	3.9	0.55
20°	3.5	0.52
30°	3.28	0.48
40°	3.1	0.44
50°	2.84	0.44
60°	2.71	0.48
70°	3.0	0.52
80°	3.14	0.55
90°	2.9	0.57
100°	2.43	0.54
110°	2.09	0.51






120°	1.95	0.48
130°	1.9	0.44
140°	1.88	0.42
150°	1.65	0.47
160°	1.95	0.52
170°	2.13	0.54
180°	2.37	0.57
190°	2.31	0.54
200°	2.3	0.52
210°	2.57	0.47
220°	2.88	0.43
230°	3.0	0.42
240°	3.32	0.48
250°	3.82	0.52
260°	4.14	0.54
270°	4.55	0.57
280°	4.39	0.54
290°	4.46	0.51
300°	4.66	0.48
310°	4.87	0.43
320°	5.11	0.43
330°	4.81	0.48
340°	4.84	0.52
350°	4.69	0.54

## Topographic roughness index (TRI)

The Topographic Roughness Index (TRI) is a measure used to quantify the ruggedeness or the unevenness of terrain. It reflects how much elevation change over a given area.





## **Topographic profiles**

