


Crater report 1870 of RG5

General information



ID: 1870

Study area: RG5

Swirl: on-swirl

Morphology: Bowl-shaped

Mean Diameter: 183m ± 11.0m

Mean depht: $10.9m \pm 0.6m$

d/D ratio: 0.059 ± 0.005

Circularity index: 0.91

Mean slope: 7.83

Geometric center coordinates: (3643912.04,

233403.4243)

Coordinates of the crater's lowest point : (3643922.4999999, 233387.49999999042)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	7.69	0.2
10°	7.57	0.2
20°	7.38	0.18
30°	7.54	0.19
40°	7.78	0.18
50°	7.56	0.18
60°	6.91	0.19
70°	7.07	0.2
80°	7.37	0.21
90°	7.61	0.21
100°	7.47	0.19
110°	7.84	0.19
120°	8.07	0.18






130°	9.09	0.17
140°	8.48	0.17
150°	7.81	0.17
160°	7.93	0.18
170°	8.01	0.19
180°	8.02	0.2
190°	7.82	0.2
200°	7.77	0.2
210°	8.1	0.19
220°	8.6	0.19
230°	8.71	0.17
240°	7.99	0.18
250°	8.13	0.19
260°	8.4	0.19
270°	8.95	0.21
280°	8.48	0.2
290°	8.2	0.19
300°	7.99	0.19
310°	7.82	0.17
320°	7.54	0.18
330°	6.54	0.19
340°	6.5	0.2
350°	7.01	0.2

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

