


# Crater report 1426 of RG5

#### **General information**



**ID**: 1426

Study area: RG5

**Swirl**: on-swirl

Morphology: Bowl-shaped

Mean Diameter: 134m ± 9.0m

Mean depht:  $7.4m \pm 0.6m$ 

d/D ratio : 0.055 ± 0.006

Circularity index: 0.93

Mean slope: 7.34

Geometric center coordinates: (3639467.988,

238937.3761)

Coordinates of the crater's lowest point : (3639472.4999999, 238932.49999999034)

#### Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	7.36	0.25
10°	6.58	0.23
20°	6.39	0.23
30°	6.11	0.21
40°	6.48	0.2
50°	6.3	0.2
60°	6.18	0.21
70°	6.43	0.22
80°	6.55	0.22
90°	7.16	0.24
100°	7.0	0.22
110°	7.2	0.21
120°	7.27	0.21






130°	7.51	0.22
140°	8.05	0.22
150°	8.25	0.22
160°	8.05	0.22
170°	8.06	0.23
180°	7.96	0.23
190°	7.48	0.22
200°	7.17	0.21
210°	6.89	0.2
220°	7.14	0.19
230°	7.61	0.2
240°	7.65	0.21
250°	7.55	0.22
260°	7.54	0.22
270°	8.16	0.23
280°	8.07	0.23
290°	7.82	0.24
300°	7.84	0.23
310°	8.22	0.22
320°	8.15	0.22
330°	7.49	0.23
340°	7.47	0.25
350°	7.22	0.23

### **Topographic roughness index (TRI)**

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





## **Topographic profiles**

