


Crater report 4862 of RG5

General information



ID: 4862

Study area: RG5

Swirl: off-swirl

Morphology: Bowl-shaped

Mean Diameter : $123m \pm 8.0m$

Mean depht: $4.1m \pm 0.6m$

d/D ratio : 0.033 ± 0.005

Circularity index: 0.9

Mean slope: 4.26

Geometric center coordinates: (3645618.426,

199939.8354)

Coordinates of the crater's lowest point : (3645617.4999998994, 199927.4999999911)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	4.91	0.23
10°	4.88	0.21
20°	4.88	0.2
30°	4.84	0.2
40°	5.08	0.19
50°	5.0	0.2
60°	4.67	0.21
70°	4.44	0.23
80°	4.54	0.24
90°	4.69	0.25
100°	4.42	0.24
110°	4.13	0.24
120°	4.39	0.24






130°	4.61	0.25
140°	4.68	0.25
150°	4.58	0.24
160°	4.42	0.27
170°	4.47	0.28
180°	4.69	0.29
190°	4.39	0.28
200°	4.24	0.27
210°	4.46	0.27
220°	3.96	0.22
230°	3.92	0.22
240°	3.55	0.22
250°	3.6	0.23
260°	3.67	0.22
270°	3.88	0.24
280°	3.58	0.22
290°	3.34	0.21
300°	3.29	0.2
310°	3.54	0.19
320°	3.59	0.19
330°	3.7	0.21
340°	4.08	0.22
350°	4.38	0.21

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

