


# Crater report 71 of RG5

#### **General information**



**ID**:71

Study area: RG5

Swirl: off-swirl

Morphology: Bowl-shaped

Mean Diameter: 140m ± 9.0m

Mean depht :  $6.5m \pm 0.6m$ 

d/D ratio : 0.046 ± 0.005

Circularity index: 0.9

Mean slope: 7.85

Geometric center coordinates: (3634856.274,

251782.4988)

Coordinates of the crater's lowest point : (3634837.4999999, 251767.49999999008)

### Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	3.48	0.18
10°	3.16	0.19
20°	3.31	0.19
30°	4.25	0.19
40°	5.44	0.19
50°	7.38	0.22
60°	8.4	0.23
70°	10.15	0.28
80°	10.39	0.27
90°	11.15	0.28
100°	11.94	0.29
110°	10.97	0.28
120°	11.01	0.26






130°	10.28	0.24
140°	10.37	0.24
150°	10.86	0.26
160°	10.18	0.26
170°	11.89	0.29
180°	12.06	0.31
190°	11.2	0.29
200°	11.8	0.29
210°	12.53	0.32
220°	11.54	0.28
230°	9.11	0.28
240°	8.74	0.3
250°	8.16	0.28
260°	5.5	0.24
270°	5.38	0.24
280°	4.57	0.21
290°	4.25	0.19
300°	4.16	0.17
310°	4.11	0.16
320°	3.91	0.16
330°	3.66	0.16
340°	3.66	0.17
350°	3.48	0.18

## **Topographic roughness index (TRI)**

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





## **Topographic profiles**

