


# Crater report 1887 of RG7

#### **General information**



**ID**: 1887

Study area: RG7

Swirl: on-swirl

Morphology: Bowl-shaped

State of degradation: AB - B

Mean Diameter: 303m ± 9.0m

Mean depth: 43.6m + 0.6m

**Mean depht**: 43.6m ± 0.6m **d/D ratio**: 0.144 ± 0.005

Circularity index: 0.98

Mean slope: 17.2°

Geometric center coordinates:

(3624305.230214652, 227138.6695553487)

Coordinates of the crater's lowest point :

(3624307.4999999, 227132.49999999054)

### Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	17.79	0.13
10°	17.06	0.13
20°	17.08	0.12
30°	16.6	0.12
40°	18.04	0.12
50°	17.04	0.12
60°	16.63	0.12
70°	16.93	0.12
80°	17.29	0.13
90°	17.98	0.13
100°	16.97	0.13
110°	16.52	0.13






120°	16.06	0.12
130°	16.65	0.12
140°	16.84	0.12
150°	16.99	0.12
160°	17.51	0.13
170°	18.33	0.13
180°	17.66	0.13
190°	16.84	0.13
200°	16.7	0.12
210°	17.03	0.12
220°	17.63	0.12
230°	17.66	0.11
240°	17.01	0.12
250°	16.49	0.12
260°	17.1	0.13
270°	17.59	0.13
280°	17.19	0.13
290°	16.93	0.12
300°	17.04	0.12
310°	18.05	0.11
320°	18.41	0.11
330°	17.27	0.12
340°	16.7	0.12
350°	17.56	0.12

## Topographic roughness index (TRI)

The Topographic Roughness Index (TRI) is a measure used to quantify the ruggedeness or the unevenness of terrain. It reflects how much elevation change over a given area.





## **Topographic profiles**

