

# Crater report 1046 of RG5

#### **General information**



**ID**: 1046

Study area: RG5

Swirl: on-swirl

Morphology: Bowl-shaped

Mean Diameter: 126m ± 9.0m

Mean depht: 3.6m ± 0.6m

**d/D ratio** :  $0.028 \pm 0.005$ 

Circularity index: 0.9

Mean slope: 3.87

Geometric center coordinates: (3639244.934,

241366.288)

Coordinates of the crater's lowest point :

(3639252.4999999, 241352.49999999028)

#### Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	4.79	0.25
10°	4.67	0.26
20°	4.63	0.24
30°	4.74	0.25
40°	5.14	0.25
50°	5.26	0.25
60°	5.09	0.24
70°	4.85	0.25
80°	5.01	0.26
90°	5.25	0.27
100°	5.06	0.28
110°	4.88	0.27
120°	4.64	0.27






130°	4.69	0.25
140°	4.09	0.25
150°	3.81	0.24
160°	3.39	0.25
170°	3.52	0.26
180°	3.67	0.25
190°	3.58	0.24
200°	3.23	0.23
210°	3.14	0.21
220°	3.14	0.21
230°	2.98	0.19
240°	2.62	0.2
250°	2.52	0.2
260°	2.51	0.21
270°	2.55	0.22
280°	2.3	0.22
290°	2.36	0.2
300°	2.62	0.19
310°	3.03	0.19
320°	3.32	0.21
330°	3.56	0.21
340°	4.01	0.23
350°	4.53	0.24

### **Topographic roughness index (TRI)**

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





## **Topographic profiles**

