


Crater report 766 of RG5

General information



ID:766

Study area: RG5

Swirl: off-swirl

Morphology: Bowl-shaped

Mean Diameter: 192m ± 9.0m

Mean depht : $15.0m \pm 0.6m$

d/D ratio: 0.078 ± 0.005

Circularity index: 0.91

Mean slope: 10.83

Geometric center coordinates: (3643347.664,

250221.3475)

Coordinates of the crater's lowest point : (3643352.4999999, 250207.4999999901)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	11.4	0.2
10°	11.26	0.2
20°	10.76	0.19
30°	10.64	0.17
40°	11.09	0.17
50°	11.47	0.16
60°	10.63	0.17
70°	10.26	0.17
80°	10.9	0.18
90°	12.11	0.2
100°	11.74	0.19
110°	11.61	0.19
120°	11.8	0.18






130°	12.7	0.18
140°	12.93	0.18
150°	11.94	0.2
160°	12.69	0.21
170°	13.42	0.21
180°	13.0	0.22
190°	12.12	0.2
200°	11.43	0.19
210°	9.93	0.18
220°	9.66	0.17
230°	10.0	0.17
240°	9.26	0.19
250°	9.02	0.19
260°	9.24	0.19
270°	10.04	0.2
280°	9.33	0.19
290°	9.26	0.18
300°	8.83	0.17
310°	9.17	0.16
320°	9.88	0.17
330°	9.81	0.17
340°	9.92	0.18
350°	10.77	0.19

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

