

# Crater report 3268 of RG2

#### **General information**



**ID**: 3268

Study area: RG2 Swirl: off-swirl

Morphology: Bowl-shaped

Estimate state of degradation : B

Mean Diameter : 465m ± 26.0m

Mean depht: 48.9m ± 0.7m

**d/D ratio** :  $0.105 \pm 0.006$ 

Circularity index: 0.94

Slope: Between 12.18° et 19.77°

Mean value of TRI on the rim crest: 0.24

**Geometric center coordinates :** (3656432.7446953123, 209147.05446529452)

**Coordinates of the crater's lowest point :** (3656431.0000011004, 209111.0000000616)

### Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	19.77	0.55
10°	19.33	0.53
20°	18.22	0.5
30°	16.46	0.47
40°	14.91	0.43
50°	12.72	0.43
60°	12.18	0.48
70°	13.39	0.51
80°	14.95	0.54
90°	16.44	0.56
100°	16.47	0.54
110°	15.64	0.5






120°	15.37	0.48
130°	15.03	0.43
140°	14.32	0.43
150°	14.11	0.48
160°	14.65	0.51
170°	15.5	0.53
180°	16.57	0.56
190°	16.61	0.54
200°	16.6	0.51
210°	16.01	0.47
220°	16.11	0.43
230°	14.94	0.43
240°	14.5	0.47
250°	14.26	0.51
260°	14.92	0.54
270°	15.76	0.56
280°	15.51	0.54
290°	15.23	0.51
300°	15.63	0.47
310°	16.64	0.43
320°	16.46	0.43
330°	16.06	0.47
340°	16.55	0.51
350°	18.08	0.53

## Topographic roughness index (TRI)

The Topographic Roughness Index (TRI) is a measure used to quantify the ruggedeness or the unevenness of terrain. It reflects how much elevation change over a given area.





## **Topographic profiles**

