


Crater report 2298 of RG2

General information



ID: 2298

Study area: RG2 Swirl: on-swirl

Morphology: Bowl-shaped

Estimate state of degradation : B - BC

Mean Diameter: $247m \pm 9.0m$ Mean depht: $23.9m \pm 0.9m$

d/D ratio : 0.097 ± 0.005 Circularity index : 0.92

Slope: Between 11.4° et 18.69°

Mean value of TRI on the rim crest: 0.23

Geometric center coordinates : (3656403.466958864, 218212.45697864276)

Coordinates of the crater's lowest point: (3656403.0000011004, 218213.00000006435)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	15.77	0.56
10°	15.63	0.53
20°	15.41	0.51
30°	15.19	0.47
40°	14.86	0.43
50°	14.46	0.43
60°	13.19	0.48
70°	12.69	0.51
80°	12.5	0.54
90°	13.81	0.56
100°	13.65	0.54
110°	12.54	0.51






120°	12.52	0.48
130°	13.18	0.43
140°	13.11	0.43
150°	12.89	0.48
160°	13.66	0.5
170°	14.83	0.54
180°	16.51	0.56
190°	16.94	0.54
200°	16.98	0.5
210°	17.69	0.47
220°	18.53	0.42
230°	18.69	0.42
240°	17.93	0.47
250°	18.2	0.51
260°	18.17	0.54
270°	18.57	0.56
280°	17.32	0.53
290°	15.32	0.51
300°	14.08	0.47
310°	12.88	0.43
320°	11.4	0.43
330°	11.66	0.48
340°	12.64	0.51
350°	14.18	0.54

Topographic roughness index (TRI)

The Topographic Roughness Index (TRI) is a measure used to quantify the ruggedeness or the unevenness of terrain. It reflects how much elevation change over a given area.





Topographic profiles

