


Crater report 1287 of RG5

General information



ID: 1287

Study area: RG5

Swirl: on-swirl

Morphology: Bowl-shaped

Mean Diameter: 145m ± 8.0m

Mean depht: $10.6m \pm 0.6m$

d/D ratio : 0.073 ± 0.006

Circularity index: 0.92

Mean slope: 10.11

Geometric center coordinates: (3634953.292,

237043.4554)

Coordinates of the crater's lowest point : (3634962.4999999, 237032.49999999037)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	11.68	0.24
10°	10.44	0.23
20°	10.18	0.22
30°	10.22	0.2
40°	10.74	0.2
50°	11.25	0.22
60°	10.34	0.22
70°	10.14	0.22
80°	10.42	0.23
90°	11.31	0.24
100°	10.79	0.23
110°	10.01	0.22
120°	9.53	0.2






Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

