


Crater report 3799 of RG5

General information



ID: 3799

Study area: RG5

Swirl: on-swirl

Morphology: Bowl-shaped

Mean Diameter: 165m ± 8.0m

Mean depht : $9.4m \pm 0.6m$

d/D ratio : 0.057 ± 0.005

Circularity index: 0.93

Mean slope: 6.9

Geometric center coordinates: (3639286.709,

206880.1207)

Coordinates of the crater's lowest point : (3639292.4999999, 206887.49999999998)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	8.25	0.21
10°	7.28	0.21
20°	6.65	0.2
30°	6.01	0.19
40°	5.54	0.18
50°	5.37	0.18
60°	5.03	0.18
70°	5.2	0.19
80°	5.38	0.19
90°	5.93	0.2
100°	5.99	0.2
110°	5.95	0.19
120°	6.01	0.19






130°	6.65	0.19
140°	7.14	0.19
150°	7.77	0.2
160°	7.97	0.19
170°	8.25	0.19
180°	8.41	0.2
190°	7.18	0.18
200°	6.62	0.18
210°	5.83	0.17
220°	5.56	0.16
230°	5.48	0.16
240°	5.89	0.18
250°	6.53	0.19
260°	7.33	0.2
270°	8.16	0.21
280°	8.03	0.21
290°	7.93	0.2
300°	7.94	0.2
310°	8.67	0.19
320°	8.66	0.19
330°	8.11	0.19
340°	7.78	0.19
350°	7.91	0.2

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

