


# Crater report 453 of RG2

#### **General information**



**ID**: 453

Study area: RG2 Swirl: on-swirl

Morphology: Bowl-shaped

Estimate state of degradation : B

Mean Diameter: 165m ± 11.0m

Mean depht:  $17.8m \pm 0.4m$ 

d/D ratio : 0.108 ± 0.008 Circularity index : 0.94

Slope: Between 12.18° et 16.8°

Mean value of TRI on the rim crest: 0.19

**Geometric center coordinates :** (3659180.070343969, 233094.87816847238)

**Coordinates of the crater's lowest point :** (3659183.0000011013, 233089.0000000688)

### Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	14.35	0.56
10°	14.19	0.53
20°	13.95	0.51
30°	13.6	0.48
40°	14.19	0.43
50°	14.33	0.43
60°	14.36	0.47
70°	15.18	0.51
80°	14.75	0.53
90°	15.6	0.56
100°	14.86	0.54
110°	14.96	0.51






120°	14.9	0.48
130°	15.54	0.43
140°	16.54	0.43
150°	15.81	0.48
160°	15.97	0.51
170°	16.75	0.54
180°	16.8	0.56
190°	15.59	0.54
200°	14.92	0.51
210°	14.49	0.48
220°	14.38	0.43
230°	14.01	0.43
240°	13.16	0.48
250°	12.73	0.51
260°	12.87	0.54
270°	13.38	0.57
280°	12.36	0.54
290°	12.24	0.52
300°	12.18	0.48
310°	13.6	0.43
320°	13.74	0.43
330°	13.47	0.47
340°	13.17	0.51
350°	12.83	0.54

## Topographic roughness index (TRI)

The Topographic Roughness Index (TRI) is a measure used to quantify the ruggedeness or the unevenness of terrain. It reflects how much elevation change over a given area.





# **Topographic profiles**

