

Crater report 2922 of RG5

General information



ID: 2922

Study area: RG5

Swirl: on-swirl

Morphology: Bowl-shaped

Mean Diameter: 141m ± 9.0m

Mean depht : $10.0m \pm 0.6m$

d/D ratio : 0.071 ± 0.006

Circularity index: 0.91

Mean slope: 9.62

Geometric center coordinates: (3642893.48,

216670.1247)

Coordinates of the crater's lowest point : (3642902.4999999, 216662.49999999077)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	10.89	0.23
10°	9.95	0.22
20°	9.42	0.21
30°	8.98	0.2
40°	8.68	0.19
50°	7.77	0.18
60°	7.41	0.19
70°	7.01	0.19
80°	7.15	0.2
90°	7.59	0.21
100°	7.52	0.21
110°	7.24	0.21
120°	7.19	0.21






7.97	0.2
8.8	0.2
8.83	0.2
8.91	0.2
9.5	0.21
9.86	0.22
9.44	0.22
9.17	0.21
9.78	0.22
10.01	0.2
10.7	0.22
10.9	0.22
10.7	0.22
11.25	0.23
11.88	0.24
11.38	0.23
11.4	0.24
12.4	0.23
12.02	0.21
11.81	0.21
11.06	0.22
10.96	0.23
10.68	0.23
	8.8 8.83 8.91 9.5 9.86 9.44 9.17 9.78 10.01 10.7 10.9 10.7 11.25 11.88 11.38 11.4 12.4 12.02 11.81 11.06

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

