


Crater report 2292 of RG5

General information



ID: 2292

Study area: RG5

Swirl: on-swirl

Morphology: Bowl-shaped

Mean Diameter: 163m ± 8.0m

Mean depht: $10.4m \pm 0.8m$

d/D ratio : 0.064 ± 0.006

Circularity index: 0.92

Mean slope: 8.43

Geometric center coordinates: (3635756.264,

221556.4949)

Coordinates of the crater's lowest point :

(3635772.4999999, 221532.4999999907)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	7.15	0.25
10°	6.2	0.23
20°	6.06	0.23
30°	6.96	0.23
40°	8.14	0.22
50°	8.85	0.22
60°	9.15	0.22
70°	9.14	0.22
80°	9.53	0.23
90°	10.46	0.23
100°	10.09	0.23
110°	9.61	0.21
120°	9.41	0.21






130°	9.33	0.19
140°	9.08	0.19
150°	8.27	0.19
160°	8.04	0.19
170°	8.2	0.19
180°	8.78	0.2
190°	8.4	0.19
200°	8.15	0.17
210°	8.36	0.18
220°	8.68	0.17
230°	8.96	0.17
240°	8.81	0.18
250°	8.88	0.18
260°	9.3	0.19
270°	9.7	0.2
280°	8.98	0.19
290°	8.56	0.19
300°	8.21	0.18
310°	8.28	0.18
320°	7.49	0.18
330°	6.96	0.2
340°	6.54	0.22
350°	6.68	0.23

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

