

# Crater report 472 of RG2

#### **General information**



**ID**: 472

Study area: RG2 Swirl: on-swirl

Morphology: Bowl-shaped

Estimate state of degradation: BC

Mean Diameter :  $55m \pm 3.0m$ Mean depht :  $4.9m \pm 0.2m$ 

d/D ratio : 0.088 ± 0.007 Circularity index : 0.93

Slope: Between 9.27° et 13.68°

Mean value of TRI on the rim crest: 0.43

**Geometric center coordinates :** (3656544.2859561713, 231101.73857405034)

**Coordinates of the crater's lowest point**: (3656543.0000011004, 231103.00000006822)

### Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	10.55	0.57
10°	9.82	0.53
20°	9.48	0.5
30°	9.27	0.48
40°	10.07	0.43
50°	10.69	0.43
60°	10.25	0.46
70°	11.19	0.53
80°	11.33	0.52
90°	12.11	0.57
100°	11.53	0.53
110°	11.79	0.53






120°	11.88	0.48
130°	12.5	0.43
140°	12.14	0.43
150°	11.38	0.48
160°	12.17	0.52
170°	12.5	0.52
180°	12.88	0.56
190°	11.41	0.53
200°	10.87	0.53
210°	11.08	0.46
220°	11.74	0.43
230°	12.46	0.44
240°	11.82	0.49
250°	11.59	0.51
260°	12.86	0.54
270°	13.68	0.57
280°	12.36	0.54
290°	11.81	0.5
300°	11.55	0.49
310°	13.33	0.44
320°	12.73	0.44
330°	11.16	0.45
340°	9.9	0.5
350°	10.04	0.53

## Topographic roughness index (TRI)

The Topographic Roughness Index (TRI) is a measure used to quantify the ruggedeness or the unevenness of terrain. It reflects how much elevation change over a given area.





## **Topographic profiles**

