


# Crater report 2222 of RG2

#### **General information**



**ID**: 2222

Study area: RG2 Swirl: on-swirl

Morphology: Bowl-shaped

Estimate state of degradation : B - BC

Mean Diameter: 70m ± 3.0m Mean depht: 6.9m ± 0.5m

d/D ratio : 0.098 ± 0.009 Circularity index : 0.9

Slope: Between 11.18° et 17.0°

Mean value of TRI on the rim crest: 0.03

**Geometric center coordinates :** (3657687.630822302, 219075.06049292293)

**Coordinates of the crater's lowest point :** (3657689.000001101, 219059.00000006458)

### Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	15.4	0.56
10°	14.77	0.54
20°	15.68	0.5
30°	15.88	0.47
40°	17.0	0.42
50°	15.69	0.44
60°	15.03	0.48
70°	14.52	0.51
80°	14.55	0.55
90°	15.28	0.56
100°	14.55	0.52
110°	13.78	0.5






120°	13.18	0.48
130°	13.97	0.44
140°	13.82	0.44
150°	14.22	0.45
160°	13.53	0.54
170°	12.93	0.54
180°	13.68	0.57
190°	12.72	0.54
200°	12.66	0.53
210°	12.3	0.48
220°	11.63	0.43
230°	11.18	0.43
240°	11.55	0.48
250°	11.44	0.51
260°	11.62	0.55
270°	12.27	0.57
280°	11.83	0.55
290°	11.49	0.52
300°	11.9	0.48
310°	11.88	0.43
320°	13.2	0.43
330°	13.69	0.48
340°	13.51	0.51
350°	13.94	0.54

## Topographic roughness index (TRI)

The Topographic Roughness Index (TRI) is a measure used to quantify the ruggedeness or the unevenness of terrain. It reflects how much elevation change over a given area.





# **Topographic profiles**

