

Maintenance sheet version 9 for accumulation area (single mast, two levels)

Station name	HUM
People present	CLAN KDM NBR ANJA BAN & GUMMI / EGERT
Purpose	Maintenance / installation / take-down / quick visit / emergency
Date	2022-06-19

Notes:

AWS to do list		Check after maintenance			
Part	Shipped? (Y/N)	Replaced? (Y/N)	Number shipped/arrival	Number departure	
Radiometer	Y		213251	213256	Clean? Y / N
Iridium modem IMEI number	Y		300534063814560		
Inclinometer/compass	Y		Attached to the radiometer? Y / N		
Satellite antenna	Y		✓		
Wind sensor upper	Y		Black box pointing toward the radiometer (i.e., along the boom)? Y / N		
Wind sensor lower	Y		Black box pointing same direction as the radiometer? Y / N		
Temperature / humidity assembly upper	Y		Fan spins? Y / N Sounds, OK? Y / N		
Temperature / humidity assembly lower	Y		Fan spins? Y / N Sounds, OK? Y / N		
Sonic ranger upper	Y		Old sensor with new membrane? Y / N		
Sonic ranger lower	Y		Old sensor with new membrane? Y / N		
Thermistor string	Y				
Solar panel	Y		Clean? Y / N NB: is not effective when partially covered		
GPS antenna	Y		At top of logger enclosure? Y / N		
Data logger	Y		CR1000 or CR1000X?		
Logger enclosure	Y		Replaced (including everything inside)? Y / N New desiccant bags? Y / N		
Battery box	Y		New box? Y / N New desiccant bags? Y / N		
Mast extension inserted?	N		How many inserted? How long? Notes:		
Mast	Y		New mast? Y / N New sensor boom? Y / N		

HUM

Metadata maintenance

	Arrival	Departure
Time difference between logger clock and UTC ($\pm$ mm:ss)		0
Download data to PC and/or change SD card (wait for green light)	Y / N	Y / N
Name of logger program		GCNET V2
Screen dump of values in fast scan mode	Y / N	Y / N
Photos of mast, sensors, logger box wiring etc. (more is better)	OLD STATION Y / N	Y / N
Mast tilt towards radiometer (- if looking up)	°	0.6 °
Mast tilt across boom looking from radiometer (- if clockwise)	°	1.4° TOWARDS E
Upper boom direction with radiometer relative to north	° true/magn.	180 ° true/magn.
Lower boom perpendicular to upper boom. If not, measure.	Y / N °	Y / N °
Box on upper wind sensor exactly same direction as radiometer? If not, measure.	Y / N °	Y / N °
Box on lower wind sensor exactly same direction as radiometer? If not, measure.	Y / N °	Y / N ° ~3° WEST
Upper temperature / humidity height (bottom of casing – surface)	cm	427 cm
Lower temperature / humidity height (bottom of casing – surface)	cm	305 cm
Upper sonic ranger height (bottom of casing – surface)	cm	387.5 cm
Lower sonic ranger height (bottom of casing – surface)	cm	257 cm
Length of thermistor string on surface from surface marking	cm	16792 cm
Apparent damage to sensors? If yes, which?	Y / N	Y / N

Notes:

280143 323+102
~~THERMISTOR CABLE LENGTH. 192 cm~~

TOP T SENSOR 16 cm below surface


WS&D TOP CAPS HAD 1-2mm SPACE BETWEEN PROPELLOR AND CAP

Must-do at next visit:



ALL THE WAY TIGHT.
 PROPELLORS ARE TIGHT ON GEVING.
 NOT LIKELY TO BE AN ISSUE

THIS TRIP HAS BEEN MEASURING BOTTOM OF ASPIRATED SECTION OF CASING:



NO DESSICANT BAGS ON PLANE TODAY ;)

Page 2 of 2

ALL AROUND SUCCESSFUL STATION. GREAT WEATHER,

NO WIND, FULL SUN.