

ONLY HARD COPY !

AWS maintenance / establishment checklist version 5

Station name	2AK-T TOP STATION
Observer(s)	MCIT - DOLA
Purpose of visit	MAINT


Establishment of new AWS: Go to **Metadata** after maintenance / establishment

Metadata upon arrival

Date & time of arrival at station	
Time difference between logger clock and UTC	4s +/-
Adjust logger time to UTC	☒ Y / ☐ N
Download data to PC and/or change CF Card (wait for green light)	☒ Y / ☐ N
Download logger program to PC	☒ Y / ☐ N
Note or photograph current values in fast scan mode	☒ Y / ☐ N
Latitude (dd mm.mmm)	
Longitude (dd mm.mmm)	
Altitude (m, from GPS)	
Photos of tripod, sensors, logger box wiring etc.	☒ Y / ☐ N
Mast inclination in CNR1 direction (+ if CNR1 tilting down)	#2 °
Mast incl. across boom looking from CNR1 (- if clockwise)	+0.5 °
Boom direction relative to true/magnetic north	° true/magn
Young box direction along boom? If not, measure direction	Y / N
CNR1 aligned with mast and inclinometer? If not, measure	Y / N
Young height (center of propeller – surface)	123 cm
Rotronic height (bottom of casing – surface)	81 cm
SR50 height on AWS (membrane – surface)	7.5 / 8.5 cm
SR50 height on stakes (membrane – surface)	4.47 cm
Free length of stake – outer, holding boom with SR50	99.5 cm
Free length of stake – middle	88 cm
Free length of stake – outer, holding boom without SR50	63 cm
Length of ablation sensor tubing on the surface (to T-piece)	cm
Or: depth of ablation sensor using markings on hose	cm
Length of thermistor string on surface from surface marking	cm

AWS
BEHIND

Remarks:



Maintenance step-by-step

Change Internal battery? Data and program will be lost!	Y/ N
Change vent filter in logger enclosure?	Y/ N
Change wires or aluminum of tripod?	Y /N
Change sonic rangers membranes or replace by new sensors	Y /N/New
Align CNR1 and inclinometer with mast within 0.5°	Y/N
Clean domes and check fastenings of CNR1	Y/N
Change Hygroclip in Rotronic	Y/N
Rotronic fan OK?	Y/N
Apparent damage to Young wind sensor?	Y/N
Clean solar panel	Y/N
Voltage solar panel OK?	Y/N
Refill ablation hose?	Y/N
Redrill stakes	Y/N
Refill Ablation drinking bag (With _____ L, 100/50%)	Y/N
Redrill old ablation hose?	Y/N/new
Redrill old thermistor string?	Y/N/new
Change desiccant bags in logger box	Y/N
Change desiccant bags in battery box	Y/N
Upload new logger program? (Name: _____)	Y/N


NEW TRIPD

Remarks:

UTM
27X ~~218~~ 0480719
8284401

Metadata after maintenance / establishment


Latitude (dd mm.mmm)	
Longitude (dd mm.mmm)	
Photos of tripod, sensors, logger box wiring etc.	Y/N
Mast inclination in CNR1 direction (+ if CNR1 tilting down)	0 °
Mast incl. across boom looking from CNR1 (- if clockwise)	0 °
Boom direction relative to true/magnetic north	~0 (true) / magn
Young box direction along boom? If not, measure direction	(Y) / N
CNR1 aligned with mast and inclinometer? If not, measure	(Y) / N
Young height (center of propeller – surface)	315 cm
Rotronic height (bottom of casing – surface)	250 cm
SR50 height on AWS (membrane – surface)	230 246 cm
SR50 height on stakes (membrane – surface)	SAME cm
Free length of stake – outer, holding boom with SR50	SAME cm
Free length of stake – middle	SAME cm
Free length of stake – outer, holding boom without SR50	SAME cm
Number of 2-m pieces used for new stakes	1 / 2 / 3 / 4 / 5
Length of ablation sensor tubing on the surface (to T-piece)	N/A cm
Or: depth of ablation sensor using markings on hose	cm
Length of thermistor string on surface from surface marking	25 cm
Approximate height of surface irregularities	10 cm
Time of departure	



- ?
- buried
↓

Remarks:

New tripod - all sensors transferred



Serial numbers of hardware

SR50 Snow (sonic ranger on AWS)	
	Replaced with:
SR50 Abl (sonic ranger on stakes)	
	Replaced with:
Rotronic assembly (Assembly no. if new assembly)	
Hygroclip S3 no. 60163833	replaced with: 60687677
MP100H no.	replaced with:
RS12T (Fan) no.	replaced with:
MKRS (Arm) no.	replaced with:
NT1400 pressure transducer (Retrieved / Left in ice)	
	Replaced with:
Thermistor string (Retrieved / Left in ice) 2. (Additional) R32	
	Replaced with:
CNR1 radiation sensor	
	Replaced with:
Young wind sensor	
105094	Replaced with: NOT CHANGED
Inclinometer	
	Replaced with:
Solar Panel	
	Replaced with:
Iridium modem (if present), IMEI number:	
	Replaced with:
DC-DC Converter (SYN-DC-936)	
	Replaced with:
Satellite antenna	
	Replaced with:
GPS antenna	
	Replaced with:
In loggerbox:	
Logger Cr1000/CR10X	
	Replaced with:
Card reader CFM100	
	Replaced with:
Multiplex AM16/32	
	Replaced with:
Barometer	
	Replaced with:

Remarks: