sanas South African National Accreditation System

NON-CONFORMANCE, CORRECTIVE ACTION AND CLEARANCE REPORT

SANAS No.: T1195

Organisation Name: AZURESKY PTY LTD

NC Report Number: NC02

Area/Scope Assessed: Coal Testing

Assessor / Inspector / Expert: N Chiliza

PART 1: DETAILED OBSERVATION

At the time of Assessment Both the vessel and the lid were placed in the oven Contrary to procedure AV 004IW Where only the open vessel should go to the oven and the lid to the desiccator

Signed (Representative):

Signed (Team Leader / Inspector):

MAJOR: [X] MINOR: [ ]

Reference No. of relevant Guide / Standard / Requirement: ISO/IEC 17025 7.2

Date: 07/04/26

PART 2: ROOT CAUSE ANALYSIS

(Provide an analysis of the extent and cause of the nonconformity)

The procedure properly documents the removal of the lids and placing them in the desiccator while the crucibles are in the drying oven. This was due to negligence / oversight on the personnels part.

PART 3: CORRECTIVE ACTION TAKEN

(Clearly indicate what corrective action was taken, and attach supporting evidence of implementation)

A session was held with the personnel reminding them of the proper way to carry out the analysis of inherent moisture. A memorandum & attendance register are attached as supporting evidence of the communication.

Date: 09/04/2026

Signed (Representative):

PART 4: CORRECTIVE ACTION VERIFIED AND CLEARED

(Comment on whether the corrective action is sufficient and appropriate)

Date:

Signed: Assessor / Inspector/Expert:

PART 5: FOLLOW-UP AT NEXT ASSESSMENT

(Comment on the implementation of the corrective actions)

Date:

Signed: Assessor / Inspector/Expert:


©SANAS

AS001MF

07/25

ROOT CAUSE ANALYSIS FORM

IRQ NO: NC022



SUPERVISOR

AS004MF 07/25

BRAINSTORMING FORM

IRQ no: NC022

Brainstorming team

Nosipho N Hlongwane

TMJ Maponya

Sifiso B Nyambi

Keitumetse Maleka

Nonhlanhla P Msibi

Problem statement: At the time of assessment both the vessel and the lid were placed in the oven contrary to procedure A3004IW where only the open vessel should go to the oven and the lid to the desiccator.

Why 1: why were the crucibles placed with the lid half-open in the oven instead of alone in the oven?

None adherence to the procedure

Why 2: why was there no adherence to the procedure?

Negligence

Supervisor:

AzurESky

ATTENDANCE REGISTER

Document no:	Version:	Page:
ASMF 17043-8.4.1	0	1
Compiled by:	Sifiso Nyambi - Laboratory Manager	
Approved by:	Nonhlanhla Msibi - Operations Manager	

Date:	09/04/2025		
Chair:	Nonhlanhla M	Scribe	
Subject:	PM determination (lids to be left inside the dessicator while drying sample in oven).		
Absent:			

Present	Cell Number	Designation	Signature	Email address
NN Mlonyane	0723732558	lab Analyst		nosipho.nkulelehlonyane@gmail.com
TMJ Mapoma	0764550692	Lab Supervisor		tshepo@azuresky.it.com
SB Nyambi	0721741852	lab Manager		Sifisobernardnyambi@gmail.com
K Maleka	071 724 9031	lab analyst	Kmaleka	keitumetse@azuresky.it.com

AzurESky	**Document No.** AS008MF	**Page 1 of 1**
	Effective Date	**April 2026**
	Revision Date	**April 2029**

Title:	Memorandum	
Document by:	Azuresky Pty Ltd	**Revision No**
Compiled by:	Sifiso Nyambi & Tshepo Maponya	**00**
Authorizing Officer: N Msibi	**Signature:**	

Department: Analysis Room

Memorandum no: 001

Position: Laboratory Supervisor

Date: 09/04/2026

Title: Notice of the Deviation in the IM procedure.

During the analysis of the Moisture in analysis sample, all lids are to be placed in a pan inside the desiccator whilst the sample and crucibles are drying in the oven in accordance to clause/section 6.7 of AS004IN procedure on the determination of inherent moisture.

6.5. Uniformly spread about 1g±0.05g of the conditioned, thoroughly mixed sample (*4.1above*) into the weighing vessel.

6.6. Close the balance weighing chamber doors to allow the balance to stabilise and record the mass (m2) by pressing the space bar of the computer to enter the mass into LIMS.

6.7. Remove the lid and place them in the desiccator and heat the uncovered vessels in the moisture oven maintaining a temperature of 105° to 110°C (*4.1 above*) for 2½hours.

6.8. After a period of 2½ hours, remove the weighing vessel from the oven, replace the lid and allow cooling on a metal plate on the work bench top for 10 minutes then transfer the weighing vessel into a desiccator for a further period of 10 minutes and weigh (m3).

6.9. Enter the masses into LIMS corresponding to the numbered weighing vessel as originally been entered by pressing the space bar of the computer.

NOTE: Samples must be placed in the oven quickly to avoid long exposure to the air as this could cause the sample to reabsorb moisture from the atmosphere. Ensure that the temperature of 105°C to 110°C is maintained for 2½ hours.

6. Result expression and calculations

M1= Mass of empty crucible
M2= mass of samples
M3= Mass of crucible+sample

%Inherent Moisture = $\frac{M3-M1}{M2} X100$

All results are reported are in an air-dry basis

Repeatability criteria:

- IM content ≤ 5% RL of 0.10%
- IM content >5% RL of 0.15%