House Rental and Property Listing System register.php has File Upload(RCE) Vulnerability


There is a file upload (RCE) vulnerability in the House Rental and Property Listing System. The vulnerability exists in the btn_functions.php file, which can upload any file format and execute any code to access the server.

Apartment Room			
Apartment Name	Mobile	Alternat Mobile	
Apartment Name	10 digit mobile number	10 digit mobile number	
Email	Plot Number/Home Number		
Email	Plot Number/Home Number		
Country	State	City	
Country	State	City	
Landmark	Address		
landmark	Address		
Image 选择文件 未选择文件 Add More(Plat Number/Description)			

Individual Home Registration

Apartment Registration

	Apartment Room	
Apartment Name	Mobile	Alternat Mobile
123	1234567890	1234567890
Email	Plot Number/Home Number	
test@qq.com	1	
Country	State	City
中国	1	1
Landmark	Address	
1	1	
Image 选择文件 test.php		
Add More(Plat Number/Description)		



Complaint

U


> | [

Z

<3 | <=



全 | 192.168.106.128/home/app/uploads/test.php



me Text (UNREGISTERED)

```
testphp x

1 <2php phpinfo(); ??
```

```
//upload an images
$target_file = "";
if (isset($_FILES["image"]["name"])) {
    $target_file = "uploads/".basename($_FILES["image"]["name"]);
    $upload0k = 1;
    $imageFileType = strtolower(pathinfo($target_file,PATHINFO_EXTENSION));
    // Check if image file is a actual image or fake image
    $check = getimagesize($_FILES["image"]["tmp_name"]);
    if($check !== false) {
        move_uploaded_file($_FILES["image"]["tmp_name"], "uploads/" . $_FILES["image"]["name"];
        $upload0k = 1;
    } else {
        echo "File is not an image.";
        $upload0k = 0;
    }
}
//end of image upload
```