



PSU rotation-40 development baseline | frozen support CGLS field

Real BOS observations; no volumetric truth, no candidate comparison, no final-audit rotation opened.

Held-out image-space mismatch



Signal amplitude is underpredicted



Tail residual by physical camera

