SYNC 3.15.89

Date: September 21st, 2018.

Description: This is an assessment of the software SYNC 3.15.89 (Evidence_SYNC_Setup.exe). Initially, was identified a few red flags regarding the timestamp and the size of the raw data. Further analysis revealed the presence of a TLS call back function and connections with suspicious files and websites.


The main components reviewed in the software included the sync.exe, taskkill.exe, imm32.dll, driver package installers and the msiexec.exe files.


The software was considered malicious and vulnerable to documented attacks techniques such as process injection and query registry.

Table of Contents

File Identification	2
Initial Assessment	5
Analysis	/
Attack	. 13


File Identification






Initial Assessment

1. The size and timestamp were considered suspicious in the static analysis¹:





¹ https://valkyrie.comodo.com/get_info?sha1=3E60678EF6AF298323C7865FAB35EDBEBE530AA3

This is the timestamp:




The PE Sections, shows some relevant information such as the size of the raw data and confirm the possibility of processing errors.







2. The PE section on the previous item, also shows the BSS section with a zero value and the identification of the TLS section referencing to a callback table.




TLS section² is further identified when the file is decompressed. This could be later referred to the SYNC.exe³ file in the aspects of a TLS call back⁴ function and importation of suspicious application programming interface (API).



The SYNC.exe make changes in the registry locations when decompressed.



3. Some network security risks were identified, mainly related to two websites:





² https://www.fireeye.com/blog/threat-research/2017/11/ursnif-variant-malicious-tls-callback-technique.html ³ https://www.hybrid-


analysis.com/sample/c7d3e5cd27afa2d7f613ddeb4f3898ae295eca20b343591d710a8fd4903d0432/5ba103287ca3 e147ff34f9c6


⁴ https://isc.sans.edu/diary/How+Malware+Defends+Itself+Using+TLS+Callback+Functions/6655

Which could download or reference to other websites and suspicious files.










Analysis

1. The software has some anti-detection files like taskkill.exe⁵

```
202] ASSIGN Base[6], ['']
                                                    [464] ASSIGN Base[5], [0]
                                                    [479] PUSHTYPE 8(String) // 6
[217] PUSHTYPE 8(String) // 7
                                                    [484] ASSIGN Base[6], ['
[222] ASSIGN Base[7], ['/f /im SYNC.exe']
                                                    [499] PUSHTYPE 8(String) // 7
[252] PUSHTYPE 8(String) // 8
                                                    [504] ASSIGN Base[7], ['/f /im SYNC.exe']
[257] ASSIGN Base[8], ['taskkill.exe']
                                                    [534] PUSHTYPE 8(String) // 8
[284] PUSHTYPE 8(String) // 9
                                                    [539] ASSIGN Base[8], ['taskkill.exe']
                                                    [566] PUSHIYPE 8(String) //
[289] ASSIGN Base[9], ['open']
                                                    [571] ASSIGN Base[9], ['open']
[308] PUSHVAR Base[2] // 10
                                                    [590] PUSHVAR Base[2] // 10
[314] CALL 33
                                                    [596] CALL 33
[319] POP // 9
                                                    [601] POP // 9
[320] POP // 8
                                                    [602] POP // 8
[321] POP // 7
                                                    [603] POP // 7
```

2. The file IMM32.dll⁶ shows a process error and this could adversely impact the computer system:



⁵ https://docs.microsoft.com/en-us/previous-versions/windows/it-pro/windows-xp/bb491009(v=technet.10)


7

⁶ https://www.processlibrary.com/en/directory/files/imm32/22508/



Then we see that the software shows the presence of two threads that allows to import additional *.dll files.







This second thread could be related to the driver installation (dpinst,2) which also execute a search on administrator settings:




3. The driver package installer "dpinst,1" (after decompression) could represent some security risks⁷, despite the fact of being whitelisted⁸:





 $^{^7} https://www.virustotal.com/\#/file/cdd0b13eefadc1ad1fd815d188c377671c46a6822ee95590aca19f83b112c5f5/relations$

⁸ https://www.hybridanalysis.com/sample/cdd0b13eefadc1ad1fd815d188c377671c46a6822ee95590aca19f83b112c5f5/5ba14f497ca3e 111c36bf665



While the driver package installer⁹ "dpinst,2" shows some ambiguous¹⁰ behavior, which could be associated with the file 996E.exe¹¹:



⁹https://www.virustotal.com/#/file/cf2910e87e064c5b1beec56c6603750bbb579548bafe8b30095920de2f9b4a30/behavior

¹⁰ https://www.hybrid-

analysis.com/sample/cf2910e87e064c5b1beec56c6603750bbb579548bafe8b30095920de2f9b4a30/57d22b4daac2ed54468e6e2d


¹¹ http://www.exefilesupport.com/easy-guide-to-remove-996e-exe-from-pc



And the Kernel32 function DeviceloControl 12:

```
@52f937: call dword ptr [004E11ACh] ;DeviceIoControl@KERNEL32.DLL
@52f93d: push esi
```

4. Finally, changes in the registry are possibly due to the file install_script.iss observed after decompressing the executable file.



For instance, there was a change related to the file msiexec.exe¹³ which gives full control over the installation process:


Further analysis is also recommended for the other registries such as Current User, Classes Root, and Users.

¹² https://msdn.microsoft.com/en-us/library/windows/desktop/aa363216(v=vs.85).aspx


¹³ https://www.advancedinstaller.com/user-guide/msiexec.html

Attack

These were the identified risks¹⁴:



These are the documented attack techniques identified:



¹⁴ https://www.hybrid-

analysis.com/sample/fd574ef4edc93657dc9bdd5d132e3481eace05b5b336aecf7be29768ec51c54c/5b05353d7ca3e159605736d9