
Transformer SE3_TP4

Transformer's age: 27

Load and Power Factor






Figure 1: Graphic with load factor

Figure 2: Graphic with power factor

Furfural





Figure 3: Graphic with quantity

Oil Quality




0.08 - acidity

0.07 - 0.06 - 0.05 - 0.04 - 0.03 - 0.02 - 0.01 - 1996 2000 2004 2008 2012 2016

Figure 4: Graphic with breakdown voltage

Figure 5: Graphic with acidity







Figure 6: Graphic with interfacial tension, water content

Figure 7: Graphic with color

Dissolved Gases






Figure 8: Graphic with ch4, c2h4, c2h6, c2h2

Figure 9: Graphic with co




Figure 10: Graphic with h2, coh2

Overall Condition




Figure 11: Graphic with score

Health Index





Figure 12: Graphic with Algorithm 2, Algorithm 4, Algorithm 3, Algorithm 1



Overall Condition

connectors, oil level