

Vendor	150644 Iberica Fruit Cooperation SL c / Universidad 4, Pta 4 46003 VALENCIA Spain							
Quality Control Report No.	QR-19-016623	Consignment No. PO-19-009124						
QC Date	15-02-19							
Checkpoint	INTAKE							
Certificate	ES-ECO-001	Comments Vendor						
Controller	royz							
Sample Temperature	9,2 °C	The products are checked according to the UNECE standards.						
Sea Container	Description	Country of Origin	Size	Class	Unit	Packaging	Net weight	Quantity
	Organic - Butternut Pumpkins	ES	M 800-12 I		400KG	400BIN02	400	24

CONCLUSION

poor	●	
------	------------------------------------	--

Comments:

					Remarks
MAJOR DEFECTS					
Decay	5%				4% decay 1% not intact
Major pest damage	0%				
Summary	poor	●			
MINOR DEFECTS					
Pest or pest damage	0%				
Damage	4%				
Soft	0%				
Scarring	2%				
Split fruit	1%				
Dirty fruit or vegetables	15%				
Other defects	0%				
Summary	moderate	●			
LABELINFO					
Imported by eosta, legal information etc	good				
Organic certification body mentioned	good				
Summary	good	●			
ORGANIC					
Organic or transition	organic				
SIZE					
Size	moderate				600-1600g
Summary	moderate	●			
PACKAGING (if applicable)					
Packaging, box or pallet	good				
Packaging, punnet or film	good				
Summary	good	●			
COLOUR					
	good				
Summary	good	●			
FIRMNESS					
	firm to tender				
Summary	good	●			
SHELF LIFE					
	short term				
Summary	poor	●			
TRANSPORT					
	good				
Summary	good	●			

Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016623

DSCN4396.JPG



DSCN4397.JPG



DSCN4398.JPG




DSCN4399.JPG



DSCN4400.JPG



DSCN4401.JPG



Quality Control Report PO-19-009124

Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016623

DSCN4402.JPG



DSCN4403.JPG



DSCN4404.JPG



15-2-2019 11:50:48

DSCN4405.JPG



DSCN4406.JPG



DSCN4407.JPG



Quality Control Report PO-19-009124

Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016623

DSCN4408.JPG



DSCN4409.JPG



DSCN4410.JPG



DSCN4411.JPG



DSCN4412.JPG



DSCN4413.JPG



Quality Control Report PO-19-009124

Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016623

DSCN4414.JPG



DSCN4415.JPG



DSCN4416.JPG



DSCN4417.JPG



DSCN4418.JPG



DSCN4419.JPG



Quality Control Report PO-19-009124

Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016623

DSCN4420.JPG



DSCN4421.JPG



DSCN4422.JPG



DSCN4423.JPG



DSCN4424.JPG



DSCN4425.JPG



Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. **QR-19-016623**

DSCN4426.JPG



DSCN4427.JPG



DSCN4428.JPG



DSCN4429.JPG



DSCN4430.JPG

