

| | | |
|----------------------------|---|--|
| Vendor | 150644 Iberica Fruit Cooperation SL c / Universidad 4, Pta 4 46003 VALENCIA Spain | |
| Quality Control Report No. | QR-19-016206 | Consignment No. PO-19-004664 |
| QC Date | 28-01-19 | |
| Checkpoint | INTAKE | |
| Certificate | ES-ECO-001 | Comments Vendor |
| Controller | royz | |
| Sample Temperature | 9 °C | The products are checked according to the UNECE standards. |

| Sea Container | Description | Country of Origin | Size | Class | Unit | Packaging | Net weight | Quantity |
|---------------|------------------------|-------------------|------|-------|------|-----------|------------|----------|
| | Organic Sweet Potatoes | ES | L1 | I | 9KG | OT604010 | 9 | 400 |
| | Organic Sweet Potatoes | ES | L | I | 10KG | OT604011 | 10 | 0 |

CONCLUSION

| | | |
|------|------------------------------------|--|
| poor | ● | |
|------|------------------------------------|--|

Comments:

Unpure product
 Underweight found on box weight (below 9kg)
 Party with comsmetic problems by scarring

| | | | | | Remarks |
|--|----------------|---|--|--|--|
| MAJOR DEFECTS | | | | | |
| Decay | 2% | | | | |
| Major pest damage | 0% | | | | |
| Summary | moderate | ● | | | |
| MINOR DEFECTS | | | | | |
| Pest or pest damage | 4% | | | | Insect holes |
| Damage | 3% | | | | |
| Soft | 0% | | | | |
| Scarring | 15% | | | | |
| Split fruit | 0% | | | | |
| Dirty fruit or vegetables | 60% | | | | Unpure (sand/dry mud) |
| Other defects | 2% | | | | root hairs |
| Summary | poor | ● | | | |
| LABELINFO | | | | | |
| Imported by eosta, legal information etc | good | | | | |
| Organic certification body mentioned | good | | | | |
| Summary | good | ● | | | |
| ORGANIC | | | | | |
| Organic or transition | organic | | | | |
| SIZE | | | | | |
| Size | moderate | | | | up to 8% outside size sorting (under/upper) size |
| Summary | moderate | ● | | | |
| PACKAGING (if applicable) | | | | | |
| Packaging, box or pallet | poor | | | | Pallets collapsed |
| Packaging, punnet or film | good | | | | |
| Summary | poor | ● | | | |
| WEIGHT | | | | | |
| Underweight | 10 boxes | | | | |
| Amount checked | 10 boxes | | | | |
| Lowest Weight | 8.765 gr. | | | | |
| Expected weight | 9.000 gr. | | | | |
| COLOUR | | | | | |
| | good | | | | |
| Summary | good | ● | | | |
| FIRMNESS | | | | | |
| | firm to tender | | | | |
| Summary | good | ● | | | |
| SHELF LIFE | | | | | |
| | short term | | | | |
| Summary | poor | ● | | | |
| TRANSPORT | | | | | |
| | good | | | | |
| Summary | good | ● | | | |

Quality Control Report PO-19-004664

Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016206

DSCN3066.JPG




DSCN3067.JPG



DSCN3068.JPG



DSCN3069.JPG



DSCN3070.JPG



DSCN3071.JPG



Quality Control Report PO-19-004664

Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016206

DSCN3072.JPG



DSCN3073.JPG



DSCN3074.JPG



DSCN3075.JPG



DSCN3076.JPG



DSCN3077.JPG



Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016206

DSCN3078.JPG



DSCN3079.JPG



DSCN3080.JPG



DSCN3081.JPG



DSCN3082.JPG



DSCN3083.JPG



Quality Control Report PO-19-004664

Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016206

DSCN3085.JPG



DSCN3086.JPG



DSCN3087.JPG



DSCN3088.JPG



DSCN3089.JPG



DSCN3090.JPG



Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. **QR-19-016206**

DSCN3091.JPG



DSCN3092.JPG



DSCN3093.JPG



DSCN3094.JPG



DSCN3095.JPG

