

Vendor	150644 Iberica Fruit Cooperation SL c / Universidad 4, Pta 4 46003 VALENCIA Spain	
Quality Control Report No.	QR-19-016786	Consignment No. PO-19-010142
QC Date	22-02-19	
Checkpoint	INTAKE	
Certificate	???	Comments Vendor
Controller	royz	
Sample Temperature	12,5 °C	The products are checked according to the UNECE standards.

Sea Container	Description	Country of Origin	Size	Class	Unit	Packaging	Net weight	Quantity
	Organic - Butternut Pumpkins	ES	M 800-12 I		10KG	OT503018	10	420

CONCLUSION

poor	●	
------	------------------------------------	--

Comments:

					Remarks
MAJOR DEFECTS					
Decay	20%				15-20%
Major pest damage	0%				
Summary	poor	●			
MINOR DEFECTS					
Pest or pest damage	0%				
Damage	4%				
Soft	0%				
Scarring	4%				
Split fruit	0%				
Dirty fruit or vegetables	20%				
Other defects	0%				
Summary	poor	●			
LABELINFO					
Imported by eosta, legal information etc	poor				Bio-landcode unreadable
Organic certification body mentioned	good				
Summary	poor	●			
ORGANIC					
Organic or transition	organic				
SIZE					
Size	poor				560-1600g
Summary	poor	●			
PACKAGING (if applicable)					
Packaging, box or pallet	good				
Packaging, punnet or film	good				
Summary	good	●			
WEIGHT					
Underweight	2 boxes				
Amount checked	5 boxes				
Lowest Weight	8.105 gr.				
Expected weight	10.000 gr.				
COLOUR					
	good				
Summary	good	●			
FIRMNESS					
	firm to tender				
Summary	good	●			
SHELF LIFE					
	short term				
Summary	poor	●			
TRANSPORT					
	good				
Summary	good	●			

Quality Control Report PO-19-010142

Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016786

DSCN5305.JPG



DSCN5306.JPG



DSCN5307.JPG



22-2-2019 14:51:37

DSCN5308.JPG



DSCN5309.JPG



DSCN5310.JPG



Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. **QR-19-016786**

DSCN5311.JPG



DSCN5312.JPG



DSCN5313.JPG



DSCN5314.JPG



DSCN5315.JPG



DSCN5316.JPG



Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. **QR-19-016786**

DSCN5317.JPG



DSCN5318.JPG



DSCN5319.JPG



DSCN5320.JPG



DSCN5321.JPG




DSCN5322.JPG



Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016786

DSCN5323.JPG



DSCN5324.JPG



DSCN5325.JPG



DSCN5326.JPG

DSCN5326.JPG



DSCN5327.JPG



DSCN5328.JPG



Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. **QR-19-016786**

DSCN5329.JPG



DSCN5332.JPG



DSCN5330.JPG



DSCN5333.JPG



DSCN5331.JPG

