

Vendor	<b>150644</b> <b>Iberica Fruit Cooperation SL</b> c / Universidad 4, Pta 4 46003 VALENCIA Spain							
Quality Control Report No.	<b>QR-19-016156</b>	Consignment No.  <b>PO-19-004346</b>						
QC Date	25-01-19							
Checkpoint	INTAKE							
Certificate	ES-ECO-002	Comments Vendor						
Controller	anthony							
Sample Temperature	9 °C	The products are checked according to the UNECE standards.						
Sea Container	Description	Country of Origin	Size	Class	Unit	Packaging	Net weight	Quantity
	Organic Sweet Potatoes	ES	L	I	18KG	DD604018	18	240
	Organic Sweet Potatoes	ES	M	I	6KG	OT403015	6	300

## CONCLUSION

poor	<input checked="" type="radio"/>	
------	----------------------------------	--


Comments:	
At times some un purity on produce	
Frequent scarring	
Frequent sprouting	
Some mould found	

				Remarks
<b>MAJOR DEFECTS</b>				
Decay	2%			
Major pest damage	0%			
Summary	moderate	●		
<b>MINOR DEFECTS</b>				
Pest or pest damage	4%			
Damage	0%			
Soft	0%			
Scarring	15%			
Split fruit	0%			
Dirty fruit or vegetables	10%			
Other defects	15%			Sprouting
Summary	poor	●		
<b>LABELINFO</b>				
Imported by eosta, legal information etc	good			
Organic certification body mentioned	good			
Summary	good	●		
<b>ORGANIC</b>				
Organic or transition	organic			
<b>SIZE</b>				
Size	good			
Summary	good	●		
<b>PACKAGING (if applicable)</b>				
Packaging, box or pallet	good			
Packaging, punnet or film	good			
Summary	good	●		
<b>COLOUR</b>				
	good			
Summary	good	●		
<b>FIRMNESS</b>				
	firm to tender			
Summary	good	●		
<b>SHELF LIFE</b>				
	medium term			
Summary	good	●		
<b>TRANSPORT</b>				
	good			
Summary	good	●		

# Quality Control Report PO-19-004346

Vendor **150644**  
Iberica Fruit Cooperation SL  
Quality Control Report No. QR-19-016156

IMG\_5934.JPG



IMG\_5937.JPG



IMG\_5935.JPG



IMG\_5938.JPG



IMG\_5936.JPG



IMG\_5939.JPG



**Vendor** 150644  
**Iberica Fruit Cooperation SL**  
**Quality Control Report No.** QR-19-016156

IMG\_5940.JPG



IMG\_5943.JPG



IMG\_5941.JPG



IMG\_5944.JPG



IMG\_5942.JPG



IMG\_5945.JPG



# Quality Control Report PO-19-004346

Vendor **150644**  
Iberica Fruit Cooperation SL  
Quality Control Report No. QR-19-016156

IMG\_5946.JPG



IMG\_5947.JPG



IMG\_5948.JPG



IMG\_5949.JPG



IMG\_5950.JPG



IMG\_5951.JPG



Vendor **150644**  
**Iberica Fruit Cooperation SL**  
Quality Control Report No. **QR-19-016156**

IMG\_5952.JPG



IMG\_5953.JPG



IMG\_5954.JPG

