

Vendor	150644 Iberica Fruit Cooperation SL c / Universidad 4, Pta 4 46003 VALENCIA Spain							
Quality Control Report No.	QR-19-016388	Consignment No. PO-19-006341						
QC Date	05-02-19							
Checkpoint	INTAKE							
Certificate	ES-ECO-024	Comments Vendor						
Controller	ramon							
Sample Temperature	10,9 °C	The products are checked according to the UNECE standards.						
Sea Container	Description	Country of Origin	Size	Class	Unit	Packaging	Net weight	Quantity
	Organic - Butternut Pumpkins	ES	M 800-12 I		10KG	OT403020	10	800

CONCLUSION

poor	●	
------	------------------------------------	--

Comments:

the pumpkins are very dusty
and i found watery decay spots beneath
the skin. this will shorten the shelflife
Rejected

					Remarks
MAJOR DEFECTS					
Decay	0%				
Major pest damage	0%				
Summary	good	●			
MINOR DEFECTS					
Pest or pest damage	3%				
Damage	0%				
Soft	0%				
Scarring	5%				
Split fruit	0%				
Dirty fruit or vegetables	10%				
Other defects	10%				watery decay beneath skin
Summary	poor	●			
LABELINFO					
Imported by eosta, legal information etc	good				
Organic certification body mentioned	good				
Summary	good	●			
ORGANIC					
Organic or transition	organic				
SIZE					
Size	good				
Summary	good	●			
PACKAGING (if applicable)					
Packaging, box or pallet	good				
Packaging, punnet or film	good				
Summary	good	●			
COLOUR					
	good				
Summary	good	●			
FIRMNESS					
	firm to tender				
Summary	good	●			
SHELF LIFE					
	short term				
Summary	poor	●			
TRANSPORT					
	good				
Summary	good	●			

Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016388

DSCN7877.JPG



DSCN7878.JPG



DSCN7879.JPG



DSCN7880.JPG

DSCN7880.JPG



DSCN7881.JPG




DSCN7882.JPG



Vendor 150644
Iberica Fruit Cooperation SL

Quality Control Report No. QR-19-016388

DSCN7883.JPG




DSCN7884.JPG



DSCN7885.JPG



DSCN7886.JPG



DSCN7887.JPG



DSCN7888.JPG




Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016388

DSCN7889.JPG



DSCN7890.JPG



DSCN7891.JPG



DSCN7892.JPG

