

Vendor	150644 Iberica Fruit Cooperation SL c / Universidad 4, Pta 4 46003 VALENCIA Spain							
Quality Control Report No.	QR-19-016514	Consignment No. PO-19-008039						
QC Date	11-02-19							
Checkpoint	INTAKE							
Certificate	ES-ECO-001	Comments Vendor						
Controller	anthony							
Sample Temperature	14 °C	The products are checked according to the UNECE standards.						
Sea Container	Description	Country of Origin	Size	Class	Unit	Packaging	Net weight	Quantity
	Organic Sweet Potatoes	ES	L	I	18KG	OT604018	18	360
	Organic Sweet Potatoes	ES	M	I	6KG	OT403015	6	300

CONCLUSION

poor	●	
------	------------------------------------	--

Comments:

Rejected
 Decay; mould + rot found
 Undersized produce in size L, oversized in size M
 Unpurity found; Sand + dry mud
 Frequent scarrings
 Sprouting
 Short shelflife

					Remarks
MAJOR DEFECTS					
Decay	10%				
Major pest damage	0%				
Summary	poor	●			Mould + rot
MINOR DEFECTS					
Pest or pest damage	0%				
Damage	5%				
Soft	0%				
Scarring	20%				
Split fruit	0%				
Dirty fruit or vegetables	15%				
Other defects	10%				Sprouting
Summary	poor	●			
LABELINFO					
Imported by eosta, legal information etc	good				
Organic certification body mentioned	good				
Summary	good	●			
ORGANIC					
Organic or transition	organic				
SIZE					
Size	moderate				
Summary	moderate	●			Some underweight produce, <300gr in L-size
PACKAGING (if applicable)					
Packaging, box or pallet	good				
Packaging, punnet or film	good				
Summary	good	●			
COLOUR					
	good				
Summary	good	●			
FIRMNESS					
	firm to tender				
Summary	good	●			
SHELF LIFE					
	short term				
Summary	poor	●			
TRANSPORT					
	good				
Summary	good	●			

Quality Control Report PO-19-008039

Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016514

DSCN1528.JPG



DSCN1529.JPG



DSCN1530.JPG



DSCN1531.JPG



DSCN1532.JPG



DSCN1533.JPG



Quality Control Report PO-19-008039

Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. **QR-19-016514**

DSCN1534.JPG



DSCN1535.JPG



DSCN1536.JPG



DSCN1537.JPG

DSCN1537.JPG



DSCN1538.JPG



DSCN1539.JPG



Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016514

DSCN1540.JPG



DSCN1541.JPG



DSCN1542.JPG



DSCN1543.JPG



DSCN1546.JPG



DSCN1547.JPG



Quality Control Report PO-19-008039

Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016514

DSCN1548.JPG



DSCN1549.JPG



DSCN1550.JPG



DSCN1551.JPG



DSCN1552.JPG



DSCN1553.JPG



Quality Control Report PO-19-008039

Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016514

DSCN1554.JPG



DSCN1555.JPG



DSCN1556.JPG



DSCN1558.JPG



DSCN1559.JPG



DSCN1560.JPG



Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016514

DSCN1561.JPG



DSCN1562.JPG




DSCN1563.JPG



DSCN1564.JPG



DSCN1565.JPG



DSCN1566.JPG



Quality Control Report PO-19-008039

Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016514

DSCN1567.JPG




DSCN1568.JPG



DSCN1569.JPG



DSCN1570.JPG



DSCN1572.JPG



DSCN1573.JPG



Quality Control Report PO-19-008039

Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016514

DSCN1574.JPG



DSCN1575.JPG




DSCN1576.JPG



DSCN1577.JPG



DSCN1578.JPG



DSCN1579.JPG



Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016514


DSCN1580.JPG



DSCN1581.JPG



DSCN1582.JPG



DSCN1583.JPG

