

Vendor	150644 Iberica Fruit Cooperation SL c / Universidad 4, Pta 4 46003 VALENCIA Spain	
Quality Control Report No.	QR-19-016597	Consignment No. PO-19-008840
QC Date	14-02-19	
Checkpoint	INTAKE	
Certificate	ES-ECO-024	Comments Vendor
Controller	anthony	
Sample Temperature	10,4 °C	The products are checked according to the UNECE standards.

Sea Container	Description	Country of Origin	Size	Class	Unit	Packaging	Net weight	Quantity
	Organic - Butternut Pumpkins	ES	M 800-12 I		10KG	OT503018	10	1260

CONCLUSION

poor	●	
------	------------------------------------	--

Comments:

					Remarks
MAJOR DEFECTS					
Decay	3%				
Major pest damage	0%				
Summary	moderate	●			
MINOR DEFECTS					
Pest or pest damage	0%				
Damage	10%				Damages caused by stalks
Soft	0%				
Scarring	8%				
Split fruit	0%				
Dirty fruit or vegetables	10%				Unpurity found on produce
Other defects	0%				
Summary	poor	●			
LABELINFO					
Imported by eosta, legal information etc	good				
Organic certification body mentioned	good				
Summary	good	●			
ORGANIC					
Organic or transition	organic				
SIZE					
Size	good				
Summary	good	●			
PACKAGING (if applicable)					
Packaging, box or pallet	good				
Packaging, punnet or film	good				
Summary	good	●			
COLOUR					
	good				
Summary	good	●			
FIRMNESS					
	firm to tender				
Summary	good	●			
SHELF LIFE					
	short term				
Summary	poor	●			
TRANSPORT					
	good				
Summary	good	●			

Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016597

DSCN2517.JPG



DSCN2519.JPG



DSCN2520.JPG



DSCN2521.JPG

DSCN2521.JPG



DSCN2522.JPG



DSCN2523.JPG



Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. **QR-19-016597**

DSCN2524.JPG



DSCN2527.JPG



DSCN2525.JPG



DSCN2528.JPG



DSCN2526.JPG



DSCN2529.JPG



Quality Control Report PO-19-008840

Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016597

DSCN2530.JPG



DSCN2531.JPG



DSCN2532.JPG




DSCN2533.JPG



DSCN2534.JPG



DSCN2535.JPG



Vendor 150644
Iberica Fruit Cooperation SL

Quality Control Report No. QR-19-016597

DSCN2536.JPG



DSCN2537.JPG



DSCN2538.JPG



DSCN2539.JPG



DSCN2540.JPG



DSCN2541.JPG



Quality Control Report PO-19-008840

Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016597

DSCN2542.JPG



DSCN2543.JPG



DSCN2544.JPG



DSCN2545.JPG



DSCN2546.JPG



DSCN2547.JPG



Quality Control Report PO-19-008840

Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016597

DSCN2548.JPG



DSCN2549.JPG



DSCN2550.JPG



DSCN2551.JPG



DSCN2552.JPG



DSCN2553.JPG



Quality Control Report PO-19-008840

Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016597

DSCN2554.JPG



DSCN2557.JPG



DSCN2555.JPG



DSCN2558.JPG



DSCN2556.JPG



DSCN2559.JPG



Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. **QR-19-016597**

DSCN2560.JPG

