

Vendor	150644 Iberica Fruit Cooperation SL c / Universidad 4, Pta 4 46003 VALENCIA Spain	
Quality Control Report No.	QR-19-016315	Consignment No. PO-19-005875
QC Date	01-02-19	
Checkpoint	INTAKE	
Certificate	ES-ECO-001	Comments Vendor
Controller	anthony	
Sample Temperature	10,7 °C	The products are checked according to the UNECE standards.

Sea Container	Description	Country of Origin	Size	Class	Unit	Packaging	Net weight	Quantity
	Organic Sweet Potatoes	ES	-	I	8KG	OT604011	8	600

CONCLUSION

poor	●	
------	------------------------------------	--

Comments:

Rejected
 Some mould found
 Under- and oversized produce
 Sprouting
 Unpurity found frequently
 Severe scarrings + pest damages

					Remarks
MAJOR DEFECTS					
Decay	2%				Mouldformation on damaged spots
Major pest damage	0%				
Summary	moderate	●			
MINOR DEFECTS					
Pest or pest damage	5%				
Damage	0%				
Soft	0%				
Scarring	20%				
Split fruit	0%				
Dirty fruit or vegetables	30%				Unpurity
Other defects	4%				sprouting
Summary	poor	●			
LABELINFO					
Imported by eosta, legal information etc	good				
Organic certification body mentioned	good				
Summary	good	●			
ORGANIC					
Organic or transition	organic				
SIZE					
Size	poor				Under- and oversized produce
Summary	poor	●			
PACKAGING (if applicable)					
Packaging, box or pallet	good				
Packaging, punnet or film	good				
Summary	good	●			
COLOUR					
	good				
Summary	good	●			
FIRMNESS					
	firm to tender				
Summary	good	●			
SHELF LIFE					
	short term				
Summary	poor	●			
TRANSPORT					
	good				
Summary	good	●			

Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016315

IMG_6761.JPG



IMG_6764.JPG



IMG_6762.JPG




IMG_6765.JPG



IMG_6763.JPG



IMG_6766.JPG



Quality Control Report PO-19-005875

Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016315

IMG_6767.JPG



IMG_6770.JPG



IMG_6768.JPG



IMG_6771.JPG



IMG_6769.JPG



IMG_6772.JPG



Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016315

IMG_6773.JPG



IMG_6776.JPG



IMG_6774.JPG



IMG_6777.JPG



IMG_6775.JPG



IMG_6778.JPG



Quality Control Report PO-19-005875

Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016315

IMG_6779.JPG



IMG_6782.JPG



IMG_6780.JPG



IMG_6783.JPG



IMG_6781.JPG



IMG_6784.JPG



Quality Control Report PO-19-005875

Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016315

IMG_6785.JPG



IMG_6788.JPG



IMG_6786.JPG



IMG_6789.JPG



IMG_6787.JPG



IMG_6790.JPG



Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016315

IMG_6791.JPG



IMG_6794.JPG



IMG_6792.JPG



IMG_6795.JPG



IMG_6793.JPG



IMG_6796.JPG



Quality Control Report PO-19-005875

Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016315

IMG_6797.JPG



IMG_6798.JPG



IMG_6799.JPG



IMG_6800.JPG



IMG_6801.JPG



IMG_6802.JPG



Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016315

IMG_6803.JPG



IMG_6804.JPG



IMG_6805.JPG



IMG_6806.JPG



IMG_6807.JPG



IMG_6808.JPG



Quality Control Report PO-19-005875

Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016315

IMG_6809.JPG



IMG_6812.JPG



IMG_6810.JPG



IMG_6813.JPG



IMG_6811.JPG



IMG_6814.JPG



Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016315

IMG_6815.JPG



01/02/2019