

Vendor	150644 Iberica Fruit Cooperation SL c / Universidad 4, Pta 4 46003 VALENCIA Spain							
Quality Control Report No.	QR-19-015929	Consignment No. PO-19-002584						
QC Date	16-01-19							
Checkpoint	INTAKE							
Certificate	ES-ECO-001	Comments Vendor						
Controller	wijnand							
Sample Temperature	9,3 °C	The products are checked according to the UNECE standards.						
Sea Container	Description	Country of Origin	Size	Class	Unit	Packaging	Net weight	Quantity
	Organic Sweet Potatoes	ES	L	I	10KG	OT604011	10	400

CONCLUSION

poor		
------	--	--

Comments:
REJECTED Scarring 20-30% Dirty patatos 40-50% Pest or pest damage 6-10% insect holes

					Remarks
MAJOR DEFECTS					
Decay	0%				
Major pest damage	0%				
Summary	good	●			
MINOR DEFECTS					
Pest or pest damage	8%				
Damage	4%				
Soft	0%				
Scarring	20%				
Split fruit	0%				
Dirty fruit or vegetables	40%				40-50% sand
Other defects	0%				
Summary	poor	●			
LABELINFO					
Imported by eosta, legal information etc	good				
Organic certification body mentioned	good				
Summary	good	●			
ORGANIC					
Organic or transition	organic				
SIZE					
Size	good				
Summary	good	●			
PACKAGING (if applicable)					
Packaging, box or pallet	good				
Packaging, punnet or film	good				
Summary	good	●			
COLOUR					
	good				
Summary	good	●			
FIRMNESS					
	firm to tender				
Summary	good	●			
BRIX					
Summary	good	●			
PRESSURE					
Pressure	good				
SHELF LIFE					
	short term				
Summary	poor	●			
TRANSPORT					
	good				
Summary	good	●			

Quality Control Report

PO-19-002584

Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-015929

IMG_6423.JPG



IMG_6426.JPG



IMG_6424.JPG



IMG_6427.JPG



IMG_6425.JPG



IMG_6428.JPG



Vendor 150644
Iberica Fruit Cooperation SL

Quality Control Report No. QR-19-015929

IMG_6429.JPG



IMG_6432.JPG



IMG_6430.JPG



IMG_6433.JPG



IMG_6431.JPG



IMG_6434.JPG



Quality Control Report

PO-19-002584

Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. **QR-19-015929**

IMG_6435.JPG



IMG_6436.JPG



IMG_6438.JPG



IMG_6439.JPG


IMG_6439.JPG



IMG_6440.JPG



IMG_6441.JPG



Quality Control Report
PO-19-002584

Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-015929

IMG_6442.JPG



IMG_6445.JPG



IMG_6443.JPG



IMG_6447.JPG



IMG_6444.JPG



IMG_6448.JPG



Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-015929

IMG_6449.JPG



IMG_6453.JPG



IMG_6450.JPG



IMG_6454.JPG



IMG_6451.JPG



IMG_6455.JPG



Vendor **150644**
 Iberica Fruit Cooperation SL
Quality Control Report No. **QR-19-015929**

IMG_6456.JPG



IMG_6459.JPG



IMG_6457.JPG



IMG_6458.JPG

