

Vendor	150644 Iberica Fruit Cooperation SL c / Universidad 4, Pta 4 46003 VALENCIA Spain							
Quality Control Report No.	QR-19-016516	Consignment No. PO-19-007873						
QC Date	11-02-19							
Checkpoint	INTAKE							
Certificate	ES-ECO-024	Comments Vendor						
Controller	ramon							
Sample Temperature	11,8 °C	The products are checked according to the UNECE standards.						
Sea Container	Description	Country of Origin	Size	Class	Unit	Packaging	Net weight	Quantity
	Organic - Butternut Pumpkins	ES	M 800-12 I		10KG	OT503018	10	840

CONCLUSION

poor	●	
------	------------------------------------	--

Comments:

rejected
 75% underweight on boxweight
 lowest 9005gr instead of 10000gr
 15% glassy spots under the skin
 this may shorten the shelflife
 and the pumpkins are very dirty/dusty

					Remarks
MAJOR DEFECTS					
Decay	0%				
Major pest damage	0%				
Summary	good	●			
MINOR DEFECTS					
Pest or pest damage	0%				
Damage	0%				
Soft	0%				
Scarring	0%				
Split fruit	0%				
Dirty fruit or vegetables	50%				
Other defects	15%				glassy spots under the skin
Summary	poor	●			
LABELINFO					
Imported by eosta, legal information etc	good				
Organic certification body mentioned	good				
Summary	good	●			
ORGANIC					
Organic or transition	organic				
SIZE					
Size	good				
Summary	good	●			
PACKAGING (if applicable)					
Packaging, box or pallet	good				
Packaging, punnet or film	good				
Summary	good	●			
WEIGHT					
Underweight	3 boxes				
Amount checked	4 boxes				
Lowest Weight	9.005 gr.				
Expected weight	10.000 gr.				
COLOUR					
	good				
Summary	good	●			
FIRMNESS					
	firm to tender				
Summary	good	●			
SHELF LIFE					
	short term				
Summary	poor	●			
TRANSPORT					
	good				
Summary	good	●			

Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016516

DSCN8518.JPG



DSCN8521.JPG



DSCN8519.JPG



DSCN8522.JPG



DSCN8520.JPG




DSCN8523.JPG



Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016516

DSCN8524.JPG



DSCN8525.JPG



DSCN8526.JPG



DSCN8527.JPG

DSCN8527.JPG



DSCN8528.JPG



DSCN8529.JPG



Quality Control Report PO-19-007873

Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016516

DSCN8530.JPG



DSCN8531.JPG



DSCN8532.JPG



DSCN8533.JPG



DSCN8534.JPG

