

Vendor	150644 Iberica Fruit Cooperation SL c / Universidad 4, Pta 4 46003 VALENCIA Spain							
Quality Control Report No.	QR-19-016520	Consignment No. PO-19-007874						
QC Date	11-02-19							
Checkpoint	INTAKE							
Certificate	ES-ECO-001	Comments Vendor						
Controller	ramon							
Sample Temperature	8,6 °C	The products are checked according to the UNECE standards.						
Sea Container	Description	Country of Origin	Size	Class	Unit	Packaging	Net weight	Quantity
	Organic Sweet Potatoes	ES	-	I	8KG	OT604011	8	600

CONCLUSION

poor	●	
------	------------------------------------	--

Comments:

rejected
 33% underweight on boxweight
 lowest 7925gr instead of 8000gr
 11% decay/mold
 and a lot of pest damage, dirt and scarring

					Remarks
MAJOR DEFECTS					
Decay	11%				
Major pest damage	0%				
Summary	poor	●			
MINOR DEFECTS					
Pest or pest damage	15%				
Damage	6%				
Soft	0%				
Scarring	20%				
Split fruit	0%				
Dirty fruit or vegetables	0%				
Other defects	0%				
Summary	poor	●			
LABELINFO					
Imported by eosta, legal information etc	good				
Organic certification body mentioned	good				
Summary	good	●			
ORGANIC					
Organic or transition	organic				
SIZE					
Size	good				
Summary	good	●			
PACKAGING (if applicable)					
Packaging, box or pallet	poor				
Packaging, punnet or film	good				
Summary	poor	●			
WEIGHT					
Underweight	1 boxes				
Amount checked	3 boxes				
Lowest Weight	7.925 gr.				
Expected weight	8.000 gr.				
COLOUR					
	good				
Summary	good	●			
FIRMNESS					
	firm to tender				
Summary	good	●			
SHELF LIFE					
	short term				
Summary	poor	●			
TRANSPORT					
	good				
Summary	good	●			

Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016520

DSCN8535.JPG



DSCN8536.JPG



DSCN8537.JPG



DSCN8538.JPG



DSCN8539.JPG



DSCN8540.JPG



Quality Control Report PO-19-007874

Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016520

DSCN8541.JPG



DSCN8542.JPG



DSCN8543.JPG



DSCN8544.JPG

DSCN8544.JPG



DSCN8545.JPG




DSCN8546.JPG



Quality Control Report PO-19-007874

Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016520

DSCN8547.JPG



DSCN8548.JPG



DSCN8549.JPG




DSCN8550.JPG



DSCN8551.JPG



DSCN8552.JPG



Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016520

DSCN8553.JPG



DSCN8554.JPG




DSCN8555.JPG



DSCN8556.JPG

DSCN8556.JPG



DSCN8557.JPG



DSCN8558.JPG



Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. **QR-19-016520**

DSCN8559.JPG



DSCN8560.JPG



DSCN8561.JPG



DSCN8562.JPG



DSCN8563.JPG




DSCN8564.JPG



Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016520

DSCN8565.JPG



DSCN8566.JPG

