

Vendor	150644 Iberica Fruit Cooperation SL c / Universidad 4, Pta 4 46003 VALENCIA Spain							
Quality Control Report No.	QR-19-016626	Consignment No. PO-19-009126						
QC Date	15-02-19							
Checkpoint	INTAKE							
Certificate	ES-ECO-001	Comments Vendor						
Controller	royz							
Sample Temperature	11,6 °C	The products are checked according to the UNECE standards.						
Sea Container	Description	Country of Origin	Size	Class	Unit	Packaging	Net weight	Quantity
	Organic Sweet Potatoes	ES	-	I	8KG	OT604011	8	800
	Organic Sweet Potatoes Violet Flesh	ES	M	I	8KG	OT604011	8	100

CONCLUSION

poor	●	
------	------------------------------------	--

Comments:

Rapport for orange + violet
REJECTED

					Remarks
MAJOR DEFECTS					
Decay	15%				
Major pest damage	0%				
Summary	poor	●			
MINOR DEFECTS					
Pest or pest damage	60%				Insect holes
Damage	5%				
Soft	0%				
Scarring	0%				
Split fruit	0%				
Dirty fruit or vegetables	20%				Unpure/sand
Other defects	0%				
Summary	poor	●			
LABELINFO					
Imported by eosta, legal information etc	good				
Organic certification body mentioned	good				
Summary	good	●			
ORGANIC					
Organic or transition	organic				
SIZE					
Size	good				
Summary	good	●			
PACKAGING (if applicable)					
Packaging, box or pallet	good				
Packaging, punnet or film	good				
Summary	good	●			
WEIGHT					
Underweight	2 boxes				
Amount checked	5 boxes				
Lowest Weight	7.840 gr.				
Expected weight	8.000 gr.				
COLOUR					
	average				
Summary	moderate	●			
FIRMNESS					
	firm to tender				
Summary	good	●			
SHELF LIFE					
	short term				
Summary	poor	●			
TRANSPORT					
	good				
Summary	good	●			

Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016626

DSCN4431.JPG



DSCN4434.JPG



DSCN4432.JPG



DSCN4435.JPG



DSCN4433.JPG



DSCN4436.JPG



Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. **QR-19-016626**

DSCN4437.JPG




DSCN4438.JPG



DSCN4439.JPG



DSCN4440.JPG



DSCN4441.JPG



DSCN4442.JPG



Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. **QR-19-016626**

DSCN4443.JPG



DSCN4444.JPG



DSCN4445.JPG



DSCN4446.JPG

DSCN4446.JPG



DSCN4447.JPG



DSCN4448.JPG



Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016626

DSCN4449.JPG



DSCN4450.JPG



DSCN4451.JPG



DSCN4452.JPG



DSCN4453.JPG



DSCN4454.JPG



Quality Control Report PO-19-009126

Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016626

DSCN4455.JPG



DSCN4456.JPG



DSCN4457.JPG



DSCN4458.JPG



DSCN4459.JPG



DSCN4460.JPG



Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. **QR-19-016626**

DSCN4461.JPG



DSCN4462.JPG



DSCN4463.JPG



Defects observed:

- Fibrous roots at the stem end

- No other visible defects

DSCN4464.JPG



DSCN4465.JPG



DSCN4466.JPG



Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. **QR-19-016626**

DSCN4467.JPG



DSCN4468.JPG

