

Vendor	150644 Iberica Fruit Cooperation SL c / Universidad 4, Pta 4 46003 VALENCIA Spain	
Quality Control Report No.	QR-19-016478	Consignment No. PO-19-007560
QC Date	08-02-19	
Checkpoint	INTAKE	
Certificate	ES-ECO-001	Comments Vendor
Controller	anthony	
Sample Temperature	6,7 °C	The products are checked according to the UNECE standards.

Sea Container	Description	Country of Origin	Size	Class	Unit	Packaging	Net weight	Quantity
	Organic Sweet Potatoes	ES	L	I	18KG	OT604018	18	360
	Organic Sweet Potatoes	ES	M	I	6KG	OT403015	6	300

CONCLUSION

poor	●	
------	------------------------------------	--

Comments:

Some decay + mould found in the M-sized produce
 Moist produce found on size M
 Frequent sprouting in all sizes
 L-sized frequently underweight produce
 Frequent un purity + scarrings found in all sizes
 Rejected

					Remarks
MAJOR DEFECTS					
Decay	0%				
Major pest damage	0%				
Summary	good	●			
Decay	5%				Decay + mould in size M
Major pest damage	0%				
Summary	poor	●			
MINOR DEFECTS					
Pest or pest damage	5%				
Damage	0%				
Soft	0%				
Scarring	15%				
Split fruit	0%				
Dirty fruit or vegetables	10%				
Other defects	20%				Sprouting
Summary	poor	●			
LABELINFO					
Imported by eosta, legal information etc	good				
Organic certification body mentioned	good				
Summary	good	●			
ORGANIC					
Organic or transition	organic				
SIZE					
Size	poor				Size L; frequently underweight
Summary	poor	●			
PACKAGING (if applicable)					
Packaging, box or pallet	good				
Packaging, punnet or film	good				
Summary	good	●			
COLOUR					
	good				
Summary	good	●			
FIRMNESS					
	firm to tender				
Summary	good	●			
SHELF LIFE					
	medium term				
Summary	good	●			
	short term				Size M
Summary	poor	●			
TRANSPORT					
	good				
Summary	good	●			

Quality Control Report PO-19-007560

Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016478

DSCN1186.JPG



DSCN1189.JPG



DSCN1187.JPG



DSCN1190.JPG



DSCN1188.JPG



DSCN1191.JPG



Quality Control Report PO-19-007560

Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016478

DSCN1192.JPG



DSCN1193.JPG



DSCN1194.JPG



DSCN1195.JPG



DSCN1196.JPG



DSCN1197.JPG



Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. **QR-19-016478**

DSCN1198.JPG



DSCN1201.JPG



DSCN1199.JPG



DSCN1202.JPG



DSCN1200.JPG



DSCN1203.JPG



Quality Control Report PO-19-007560

Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016478

DSCN1204.JPG



DSCN1207.JPG



DSCN1205.JPG




DSCN1208.JPG



DSCN1206.JPG



DSCN1209.JPG



Quality Control Report PO-19-007560

Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016478

DSCN1210.JPG



DSCN1211.JPG



DSCN1212.JPG



DSCN1213.JPG


DSCN1213.JPG



DSCN1214.JPG



DSCN1215.JPG



Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016478

DSCN1216.JPG



DSCN1217.JPG



DSCN1218.JPG



DSCN1219.JPG

DSCN1219.JPG



DSCN1220.JPG



DSCN1221.JPG



Quality Control Report PO-19-007560

Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016478

DSCN1222.JPG



DSCN1223.JPG



DSCN1224.JPG



DSCN1225.JPG

DSCN1225.JPG



DSCN1226.JPG



DSCN1227.JPG



Quality Control Report PO-19-007560

Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016478

DSCN1228.JPG



DSCN1229.JPG



DSCN1230.JPG



DSCN1231.JPG



DSCN1232.JPG



DSCN1233.JPG



Quality Control Report PO-19-007560

Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016478

DSCN1234.JPG



DSCN1235.JPG



DSCN1236.JPG




DSCN1237.JPG



DSCN1238.JPG



DSCN1239.JPG



Quality Control Report PO-19-007560

Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016478

DSCN1240.JPG



DSCN1241.JPG



DSCN1242.JPG




DSCN1243.JPG



DSCN1244.JPG



DSCN1245.JPG



Quality Control Report PO-19-007560

Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016478

DSCN1246.JPG



DSCN1247.JPG



DSCN1248.JPG



DSCN1250.JPG



DSCN1251.JPG



DSCN1252.JPG



Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-016478

DSCN1253.JPG



DSCN1254.JPG



DSCN1255.JPG

