

Vendor	150644 Iberica Fruit Cooperation SL c / Universidad 4, Pta 4 46003 VALENCIA Spain							
Quality Control Report No.	QR-19-015971	Consignment No. PO-19-003231						
QC Date	18-01-19							
Checkpoint	INTAKE							
Certificate	ES-ECO-002	Comments Vendor						
Controller	anthony							
Sample Temperature	13 °C	The products are checked according to the UNECE standards.						
Sea Container	Description	Country of Origin	Size	Class	Unit	Packaging	Net weight	Quantity
	Organic Sweet Potatoes	ES	L	I	18KG	DD604018	18	660
	Organic Sweet Potatoes	ES	M	I	6KG	OT403015	6	600

CONCLUSION

poor		
------	--	--

Comments:

Frequently underweight fruits
 Some underweight boxes
 Sprouting and hairs
 Unpure fruits
 Frequent scarrings + damages
 Rejected

					Remarks
MAJOR DEFECTS					
Decay	2%				
Major pest damage	0%				
Summary	moderate	●			
MINOR DEFECTS					
Pest or pest damage	5%				
Damage	8%				
Soft	0%				
Scarring	20%				
Split fruit	0%				
Dirty fruit or vegetables	10%				
Other defects	0%				
Summary	poor	●			
LABELINFO					
Imported by eosta, legal information etc	good				
Organic certification body mentioned	good				
Summary	good	●			
ORGANIC					
Organic or transition	organic				
SIZE					
Size	poor				Frequently underweight fruits
Summary	poor	●			
PACKAGING (if applicable)					
Packaging, box or pallet	good				
Packaging, punnet or film	good				
Summary	good	●			
COLOUR					
	good				
Summary	good	●			
FIRMNESS					
	firm to tender				
Summary	good	●			
SHELF LIFE					
	short term				
Summary	poor	●			
TRANSPORT					
	good				
Summary	good	●			

Quality Control Report

PO-19-003231

Vendor	150644
	Iberica Fruit Cooperation SL
Quality Control Report No.	QR-19-015971

IMG_4117.JPG



IMG_4118.JPG



IMG_4119.JPG



IMG_4120.JPG



IMG_4121.JPG



IMG_4122.JPG



Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-015971

IMG_4123.JPG



IMG_4126.JPG



IMG_4124.JPG




IMG_4127.JPG



IMG_4125.JPG



IMG_4128.JPG



Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. **QR-19-015971**

IMG_4129.JPG



IMG_4130.JPG



IMG_4131.JPG



IMG_4132.JPG

IMG_4132.JPG



IMG_4133.JPG



IMG_4134.JPG



Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. **QR-19-015971**

IMG_4135.JPG



IMG_4136.JPG



IMG_4137.JPG



IMG_4138.JPG



IMG_4139.JPG



IMG_4140.JPG



Quality Control Report

PO-19-003231

Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-015971

IMG_4141.JPG



IMG_4142.JPG



IMG_4143.JPG



IMG_4144.JPG

IMG_4144.JPG



IMG_4145.JPG




IMG_4146.JPG



Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. **QR-19-015971**

IMG_4147.JPG



IMG_4148.JPG



IMG_4149.JPG



IMG_4150.JPG



IMG_4151.JPG



IMG_4152.JPG



Quality Control Report

PO-19-003231

Vendor 150644
Iberica Fruit Cooperation SL

Quality Control Report No. QR-19-015971

IMG_4153.JPG



IMG_4154.JPG



IMG_4155.JPG



IMG_4156.JPG



IMG_4157.JPG



IMG_4158.JPG



Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-015971

IMG_4159.JPG



IMG_4162.JPG



IMG_4160.JPG



IMG_4163.JPG



IMG_4161.JPG



IMG_4164.JPG



Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. **QR-19-015971**

IMG_4165.JPG



IMG_4166.JPG



IMG_4167.JPG



IMG_4168.JPG



IMG_4169.JPG



IMG_4170.JPG



**Quality Control Report
PO-19-003231**

Vendor 150644
Iberica Fruit Cooperation SL
Quality Control Report No. QR-19-015971

IMG_4171.JPG



IMG_4174.JPG



IMG_4172.JPG



IMG_4175.JPG



IMG_4173.JPG



IMG_4176.JPG



Quality Control Report

PO-19-003231

Vendor **150644**
Iberica Fruit Cooperation SL
Quality Control Report No. **QR-19-015971**

IMG_4177.JPG



IMG_4178.JPG



IMG_4179.JPG



IMG_4180.JPG



IMG_4181.JPG



IMG_4182.JPG



Vendor 150644
Iberica Fruit Cooperation SL

Quality Control Report No. QR-19-015971

IMG_4183.JPG



IMG_4186.JPG



IMG_4184.JPG



IMG_4187.JPG



IMG_4185.JPG



IMG_4188.JPG



Vendor **150644**
 Iberica Fruit Cooperation SL
Quality Control Report No. **QR-19-015971**

IMG_4189.JPG

