









NY2201.05.00A1

1 : 1



(GMYK: 75, 75, 0, 0 / RGB: 91, 87, 166 / HEX: #5B57A6)

(GMYK: 75, 75, 0, 0 / RGB: 91, 87, 166 / HEX: #5B57A6)

- Technical requirements:
- 1 with uninfested dimensions at GB/T1804-f;
 - 2 in the uninfested public space at level GB/T1184-H;
 - 3: Diagonal error <1 mm, with no significant deviation from the 'NY 2201.01 base' and as small an angle as possible on the R side;
 - Four, sharp inverted to the thorn. Unprocessed face roughness. Grave face roughness 6.3 ;
 - 5, welded evenly, welded after grinding, no pit welding, etc.;
 6. Bad appearances such as scratching, scratching, tremors, troughs, oil stains, etc.;

						SPCC t=1.0				Angéno-Tech Co. Ltd.	
										A of the upper shell.	
										NY2201.05.00A1	
Title Registry Count min Change Document Numbers Year Month Day						Order Title History Amount Example					
Set Account Standardization						S		2,361		1.5	
Process Figure Trial Number						Total 1		1		Version	
Batch Yes											