


Report ID: RDS-20260608141537

SMART ROAD DAMAGE DETECTION REPORT

AI Powered Road Inspection System

Detection Result



Parameter	Value
Total Potholes	4
Severe	0
Medium	3
Minor	1
Confidence	77.31%

Road Health Score: 65%

Road Status: ■ Fair

Image Name: 17809083007303271062329466556765.jpg

Date: 08-06-2026 14:15:37

Total Potholes: 4

Severe Potholes: 0

Medium Potholes: 3

Minor Potholes: 1

Average Confidence: 77.31%

Generated by Smart Road Damage Detection System

YOLOv8 | OpenCV | Flask