


SMART ROAD DAMAGE DETECTION REPORT

AI Powered Road Inspection System

Detection Result



Parameter	Value
Total Potholes	6
Severe	1
Medium	2
Minor	3
Confidence	76.66%

Road Health Score: 45%

Road Status: ■ Poor

Image Name: 19_jpg.rf.c4a8c4ba9d53fbbd6533420acfc1c6bc.jpg
Date: 08-06-2026 17:17:52
Total Potholes: 6
Severe Potholes: 1
Medium Potholes: 2
Minor Potholes: 3
Average Confidence: 76.66%

Generated by Smart Road Damage Detection System

YOLOv8 | OpenCV | Flask