



WebShield Security Report

Target: <https://digitalmandee.com/>

Scan Date: 8/27/2026, 1:21:30 PM

Duration: 51s

Total Vulnerabilities: 21

Status: completed


Executive Summary

Security Scan Summary

The scan identified 21 vulnerability/vulnerabilities in total. Critical: 0, High: 1, Medium: 3, Low: 17.

Immediate attention is recommended for all Critical and High severity findings. Please review each vulnerability and apply the recommended remediations.

Risk Summary



OWASP Category Breakdown

OWASP Category	Count
A05:2021 – Security Misconfiguration	15
A05:2021 - Security Misconfiguration	6

Vulnerability Findings (21 total)

Name	Risk Level	OWASP Category	AI Score	Affected URL
Missing Content-Security-Policy-Header	Medium	A05:2021 - Security Misconfiguration	N/A	https://digitalmandee.com/

Name	Risk Level	OWASP Category	AI Score	Affected URL
Missing X-Frame-Options Header	Medium	A05:2021 - Security Misconfiguration	N/A	https://digitalmandee.com/
Missing X-Content-Type-Options Header	Low	A05:2021 - Security Misconfiguration	N/A	https://digitalmandee.com/
Missing Strict-Transport-Security Header	High	A05:2021 - Security Misconfiguration	N/A	https://digitalmandee.com/
Missing Referrer-Policy Header	Low	A05:2021 - Security Misconfiguration	N/A	https://digitalmandee.com/
Missing Permissions-Policy Header	Low	A05:2021 - Security Misconfiguration	N/A	https://digitalmandee.com/
Accessible Path Discovered: /admin	Low	A05:2021 – Security Misconfiguration	N/A	https://digitalmandee.com/admin
Accessible Path Discovered: /wp-admin	Low	A05:2021 – Security Misconfiguration	N/A	https://digitalmandee.com/wp-admin
Accessible Path Discovered: /.env	Low	A05:2021 – Security Misconfiguration	N/A	https://digitalmandee.com/.env
Accessible Path Discovered: /.git/config	Low	A05:2021 – Security Misconfiguration	N/A	https://digitalmandee.com/.git/config
Accessible Path Discovered: /robots.txt	Low	A05:2021 – Security Misconfiguration	N/A	https://digitalmandee.com/robots.txt
Accessible Path Discovered: /sitemap.xml	Low	A05:2021 – Security Misconfiguration	N/A	https://digitalmandee.com/sitemap.xml
Accessible Path	Low	A05:2021 – Security Misconfiguration	N/A	https://digitalmandee.com/backup.sql

Name	Risk Level	OWASP Category	AI Score	Affected URL
Discovered: /backup.sql				
Accessible Path Discovered: /backup.bak	Low	A05:2021 – Security Misconfiguration	N/A	https://digitalmandee.com/backup.bak
Accessible Path Discovered: /config.bak	Low	A05:2021 – Security Misconfiguration	N/A	https://digitalmandee.com/config.bak
Accessible Path Discovered: /database.sql	Low	A05:2021 – Security Misconfiguration	N/A	https://digitalmandee.com/database.sql
Accessible Path Discovered: /db.sql	Low	A05:2021 – Security Misconfiguration	N/A	https://digitalmandee.com/db.sql
Accessible Path Discovered: /.htaccess	Low	A05:2021 – Security Misconfiguration	N/A	https://digitalmandee.com/.htaccess
Accessible Path Discovered: /phpinfo.php	Low	A05:2021 – Security Misconfiguration	N/A	https://digitalmandee.com/phpinfo.php
Debug or Version-Disclosure Header Present	Medium	A05:2021 – Security Misconfiguration	N/A	https://digitalmandee.com/
Email Address Exposed in Response Body	Low	A05:2021 – Security Misconfiguration	N/A	https://digitalmandee.com/

Vulnerability Details

Missing Content-Security-Policy Header

Risk Level: Medium

OWASP Category: A05:2021 - Security Misconfiguration

Affected URL: `https://digitalmandee.com/`

Affected Parameter: `Content-Security-Policy`

Description: The Content-Security-Policy security header is absent.

Missing X-Frame-Options Header

Risk Level: Medium

OWASP Category: A05:2021 - Security Misconfiguration

Affected URL: `https://digitalmandee.com/`

Affected Parameter: `X-Frame-Options`

Description: The X-Frame-Options security header is absent.

Missing X-Content-Type-Options Header

Risk Level: Low

OWASP Category: A05:2021 - Security Misconfiguration

Affected URL: `https://digitalmandee.com/`

Affected Parameter: `X-Content-Type-Options`

Description: The X-Content-Type-Options security header is absent.

Missing Strict-Transport-Security Header

Risk Level: High

OWASP Category: A05:2021 - Security Misconfiguration

Affected URL: `https://digitalmandee.com/`

Affected Parameter: `Strict-Transport-Security`

Description: The Strict-Transport-Security security header is absent.

Missing Referrer-Policy Header

Risk Level: Low

OWASP Category: A05:2021 - Security Misconfiguration

Affected URL: `https://digitalmandee.com/`

Affected Parameter: `Referrer-Policy`

Description: The Referrer-Policy security header is absent.

Missing Permissions-Policy Header

Risk Level: Low

OWASP Category: A05:2021 - Security Misconfiguration

Affected URL: https://digitalmandee.com/

Affected Parameter: Permissions-Policy

Description: The Permissions-Policy security header is absent.

Accessible Path Discovered: /admin

Risk Level: Low

OWASP Category: A05:2021 – Security Misconfiguration

Affected URL: https://digitalmandee.com/admin

Affected Parameter: /admin

Description: The path "/admin" is accessible and returned HTTP 200. Verify whether this resource should be publicly reachable. If not, restrict access via server configuration or firewall rules.

PoC Payload: HTTP 200 response for https://digitalmandee.com/admin

Accessible Path Discovered: /wp-admin

Risk Level: Low

OWASP Category: A05:2021 – Security Misconfiguration

Affected URL: https://digitalmandee.com/wp-admin

Affected Parameter: /wp-admin

Description: The path "/wp-admin" is accessible and returned HTTP 200. Verify whether this resource should be publicly reachable. If not, restrict access via server configuration or firewall rules.

PoC Payload: HTTP 200 response for https://digitalmandee.com/wp-admin

Accessible Path Discovered: /.env

Risk Level: Low

OWASP Category: A05:2021 – Security Misconfiguration

Affected URL: https://digitalmandee.com/.env

Affected Parameter: /.env

Description: The path "/.env" is accessible and returned HTTP 403. Verify whether this resource should be publicly reachable. If not, restrict access via server configuration or firewall rules.

PoC Payload: HTTP 403 response for https://digitalmandee.com/.env

Accessible Path Discovered: /.git/config

Risk Level: Low

OWASP Category: A05:2021 – Security Misconfiguration

Affected URL: `https://digitalmandee.com/.git/config`

Affected Parameter: `/.git/config`

Description: The path `"/.git/config"` is accessible and returned HTTP 403. Verify whether this resource should be publicly reachable. If not, restrict access via server configuration or firewall rules.

PoC Payload: `HTTP 403 response for https://digitalmandee.com/.git/config`

Accessible Path Discovered: `/robots.txt`

Risk Level: Low

OWASP Category: A05:2021 – Security Misconfiguration

Affected URL: `https://digitalmandee.com/robots.txt`

Affected Parameter: `/robots.txt`

Description: The path `"/robots.txt"` is accessible and returned HTTP 200. Verify whether this resource should be publicly reachable. If not, restrict access via server configuration or firewall rules.

PoC Payload: `HTTP 200 response for https://digitalmandee.com/robots.txt`

Accessible Path Discovered: `/sitemap.xml`

Risk Level: Low

OWASP Category: A05:2021 – Security Misconfiguration

Affected URL: `https://digitalmandee.com/sitemap.xml`

Affected Parameter: `/sitemap.xml`

Description: The path `"/sitemap.xml"` is accessible and returned HTTP 200. Verify whether this resource should be publicly reachable. If not, restrict access via server configuration or firewall rules.

PoC Payload: `HTTP 200 response for https://digitalmandee.com/sitemap.xml`

Accessible Path Discovered: `/backup.sql`

Risk Level: Low

OWASP Category: A05:2021 – Security Misconfiguration

Affected URL: `https://digitalmandee.com/backup.sql`

Affected Parameter: `/backup.sql`

Description: The path `"/backup.sql"` is accessible and returned HTTP 403. Verify whether this resource should be publicly reachable. If not, restrict access via server configuration or firewall rules.

PoC Payload: `HTTP 403 response for https://digitalmandee.com/backup.sql`

Accessible Path Discovered: /backup.bak

Risk Level: Low

OWASP Category: A05:2021 – Security Misconfiguration

Affected URL: `https://digitalmandee.com/backup.bak`

Affected Parameter: `/backup.bak`

Description: The path "/backup.bak" is accessible and returned HTTP 403. Verify whether this resource should be publicly reachable. If not, restrict access via server configuration or firewall rules.

PoC Payload: `HTTP 403 response for https://digitalmandee.com/backup.bak`

Accessible Path Discovered: /config.bak

Risk Level: Low

OWASP Category: A05:2021 – Security Misconfiguration

Affected URL: `https://digitalmandee.com/config.bak`

Affected Parameter: `/config.bak`

Description: The path "/config.bak" is accessible and returned HTTP 403. Verify whether this resource should be publicly reachable. If not, restrict access via server configuration or firewall rules.

PoC Payload: `HTTP 403 response for https://digitalmandee.com/config.bak`

Accessible Path Discovered: /database.sql

Risk Level: Low

OWASP Category: A05:2021 – Security Misconfiguration

Affected URL: `https://digitalmandee.com/database.sql`

Affected Parameter: `/database.sql`

Description: The path "/database.sql" is accessible and returned HTTP 403. Verify whether this resource should be publicly reachable. If not, restrict access via server configuration or firewall rules.

PoC Payload: `HTTP 403 response for https://digitalmandee.com/database.sql`

Accessible Path Discovered: /db.sql

Risk Level: Low

OWASP Category: A05:2021 – Security Misconfiguration

Affected URL: `https://digitalmandee.com/db.sql`

Affected Parameter: `/db.sql`

Description: The path "/db.sql" is accessible and returned HTTP 403. Verify whether this resource should be publicly reachable. If not, restrict access via server configuration or firewall rules.

PoC Payload: `HTTP 403 response for https://digitalmandee.com/db.sql`

Accessible Path Discovered: /.htaccess

Risk Level: Low

OWASP Category: A05:2021 – Security Misconfiguration

Affected URL: `https://digitalmandee.com/.htaccess`

Affected Parameter: `/.htaccess`

Description: The path "/.htaccess" is accessible and returned HTTP 403. Verify whether this resource should be publicly reachable. If not, restrict access via server configuration or firewall rules.

PoC Payload: `HTTP 403 response for https://digitalmandee.com/.htaccess`

Accessible Path Discovered: /phpinfo.php

Risk Level: Low

OWASP Category: A05:2021 – Security Misconfiguration

Affected URL: `https://digitalmandee.com/phpinfo.php`

Affected Parameter: `/phpinfo.php`

Description: The path "/phpinfo.php" is accessible and returned HTTP 403. Verify whether this resource should be publicly reachable. If not, restrict access via server configuration or firewall rules.

PoC Payload: `HTTP 403 response for https://digitalmandee.com/phpinfo.php`

Debug or Version-Disclosure Header Present

Risk Level: Medium

OWASP Category: A05:2021 – Security Misconfiguration

Affected URL: `https://digitalmandee.com/`

Affected Parameter: `Debug Info Header`

Description: A debug or version-disclosure header (X-Debug, X-Powered-By, or Server) was detected in the response headers of "https://digitalmandee.com/". These headers disclose technology stack details that can assist attackers in identifying known vulnerabilities. Remove or suppress these headers in production.

PoC Payload: `Detected pattern type: Debug Info Header`

Email Address Exposed in Response Body

Risk Level: Low

OWASP Category: A05:2021 – Security Misconfiguration

Affected URL: `https://digitalmandee.com/`

Affected Parameter: `Email Address Pattern`

Description: An email address pattern was detected in the response body of "https://digitalmandee.com/". Exposed email addresses can be harvested for phishing or spam campaigns. Evaluate whether this disclosure is intentional; if not, remove or obfuscate the address.

PoC Payload: Detected pattern type: Email Address Pattern

Appendix

Report generated by WebShield on 2026-08-27T08:23:47.374Z.

Scan ID: 75f57983-3b0e-4bc0-bc8d-5e262186a231