جامعة خليفة
Khalifa University

Inspection Date	07-02-2023	**Report Ref. No.**	MACINS 0X -07/2/2023
Site Name	Main campus	**Location**	OSCE A - 13,14,15,16,17,18,19,20,21,22,23,24
Inspected By	Roberto Macahig	**Witnessed by**	Ahmed Kamal Abdalgadir Mohamed

Inspection Type	☑General ☑Housekeeping & Sanitation ☑Fire ☑Electrical ☐Ladders ☑Lab ☐Food ☐Structure ☐Motor Vehicles ☐Landscaping ☐PPE ☑Stores ☑Emergency Evacuation

Findings					
	☐ Safety ☐ Environment ☐ Occupational health				
S/N	**Description**	**Significant Risk Yes/No**	**Risk Evaluation**		
			Low	**Med**	**High**
1.	Common First Aid Box and First Aiders to be available in OSCE A	No	√		
2.	Hazardous waste (Biohazard waste) management to be reviewed as bins were available, however, is actual waste will be produced on-site, and if biohazard spill kit(to be updated) is required.	Yes	√		
3.	Lab information notice, RACE C to be available in the lab (primary contact, hazards in the lab, emergency information)	Yes		√	
4.	Ceiling tiles with sharp edges were found stored in the corridor	Yes	√		
5.	Two Emergency Exit Sign lights were found defective	Yes			√
6.	Corridor Ceiling Internal smoke detector found deactivated	Yes			√

جامعة خليفة
Khalifa University

7.	One Manual call point was found deactivated	Yes			√
8.	A trolley is stored in the Emergency Exit staircase	Yes			√
9.	IDF Room Electrical Panel – related to access control is found unsecured and the room needs housekeeping.	Yes	√		
10.	Specific Risk Assessment is to be reviewed according to lab activities	Yes			√

Attachment	☑Photos	☐ Video Footage	☐Other

Corrective actions				
S/N	**Description**			
	Short Term Action	**Long Term Action**	**By Whom**	**By When**
1.	To be installed in the common area.		Lab Primary Contact	
2.	To be reviewed and decided for collection points.		Lab Primary Contact	
3.	To be installed in the common area. Signs are to be provided on-site.		Lab Primary Contact	
4.	To be removed from the site by FM Hard Services		FM - Imdaad	
5.	To be maintained by FM Hard Services		FM - Imdaad	
6.	To be maintained by FM		FM - Imdaad	

	Hard Services			
7.	To be maintained by FM Hard Services		FM - Imdaad	
8.	To be removed from the site by FM Soft Services		FM –West Coast	
9.	To be secured and maintained by FM Hard Services		FM - Imdaad	
10.	To be reviewed and updated.		Lab Primary Contact	

Prepared by: ESH Section		**Received by:**				**Followed up by:**	
		Contractor:		**Consultant:**		**☐ Corrective Action is taken**	**☐ Corrective action not taken**
Name	Roberto Macahig	Name		Name		Name	
Designation	Lab Safety Specialist	Designation		Designation		Designation	
Signature		Signature		Signature		Signature	
Date		Date		Date		Date	

Attached Photos

جامعة خليفة
Khalifa University



جامعة خليفة
Khalifa University

جامعة خليفة
Khalifa University

جامعة خليفة
Khalifa University

Copies of this document available in ADM HSE Intranet are only the latest, valid and controlled documents. All other copies are uncontrolled and valid only on the date printed. Last printed: 8/2/2023 5:29:00 PM