


Figure 10.3 Prometheus SLO in Pyrra (SLO details)

Figures 10.4 and 10.5 show the SLO for `hol1y` in Pyrra and (as configured and, hence, expected) we see the SLO of 75% breached.




Figure 10.4 The `hol1y` service SLO in Pyrra (overview)

If you would like to learn more about Pyrra, check out the excellent KubeCon 2022 talk "SLO-Based Observability for All Kubernetes Cluster Components" with Pyrra