



### Ninja Fortnite tournament

Ninja is hosting a Fortnite tournament series on Mixer where competitors can stream anywhere. <https://dgit.in/jun20-50>



### 8 billion Thai records leaked

A database of Thailand's largest cell network, AIS, leaked billions of internet records. <https://dgit.in/jun20-51>


TEARDOWN



## The primary camera lens

The standalone rear camera on the iPhone SE 2020 is largely rumoured to come from the iPhone 8 or iPhone XR. However, when all three cameras are lined up side by side you can definitely see that the SE's sensor is smaller than the XR's sensor. It may be a repurposed iPhone 8 sensor with A13 image processing. iFixit also tested fitting the iPhone 8 camera inside the SE and it reportedly works just fine.

iPhone SE  
2020



## Pop goes the motherboard

The motherboard houses the Apple A13 Bionic SoC which is layered over Samsung 3GB LPDDR4X RAM, an Avago 8100 mid/high band PAMiD (power amplifier module with integrated duplexer), an Intel 9960 P10PSV modem, a Skyworks 78223-17 power amplifier module, another Skyworks low-band PAMiD, a Cypress USB power delivery IC and 338500295 A1TR1952 5G. You can also find Toshiba 64GB flash storage, an Apple power management IC, a USI 339S00648 WiFi/Bluetooth SoC, a touch controller, and two audio ICs.



## 3D Touch-less display

As mentioned above, the 4.7" display seems to be extremely similar to the iPhone 8 display. There's one difference though, the iPhone SE display doesn't have 3D Touch. However, there is absolutely no difference in thinness despite the lack of 3D Touch, so it could just be the exact same display. On 3D Touch screens, there is usually a chip on the backside that drives the parallel plate capacitors. The new SE display doesn't have that chip, but a blank space where that chip would be. iFixit, upon testing, also confirmed that the iPhone 8 and iPhone SE 2020 displays are functionally interchangeable, however, you can't get 3D Touch to work on the SE.



Images courtesy:

**IFIXIT**

Website: [iFixit.com](https://dgit.in/iPhoneSE)

Teardown link: <https://dgit.in/iPhoneSE>