



Toshiba out of the laptop race

The iconic tech company is bowing out of the laptop market after struggling in recent times. <http://digit.in/sep20-35>



Flight stick stocks running low

After the release of Microsoft Flight Simulator, Flight sticks everywhere are selling out. <http://digit.in/sep20-36>



OnePlus Nord




Cameras for days

The OnePlus Nord doesn't hold back when it comes to its camera array, seeing that it is a huge selling point for most smartphones these days. The rear camera module pops out together and you have a 48MP Sony IMX586 primary sensor which comes with OIS (the same sensor as in the OnePlus 8). The other rear camera sensors include an 8MP ultra-wide lens with a 119-degree FOV, a 5MP depth camera and a 2MP macro camera. The front cameras include a 32MP main shooter and an 8MP ultra-wide shooter with a 105-degree FOV.



Water-resistant?

Now, the OnePlus Nord doesn't boast an official IP rating, and understandably so, seeing that IP testing and certifications are exorbitant. However, the insides reveal rubber connector gaskets which are also found in the IP68-certified OnePlus 8 Pro. The device may have some water and dust resistance but we advise you to stray away from moisture anyway when using it. Nevertheless, it is good to see the inclusion of rubber connector gaskets inside which may come in handy in case of accidents.



Examining the motherboard

To examine the silicone, some screws need to be pulled out and the motherboard can then be extracted from the device. There's also some thermal paste on the back of the mainboard which has a graphite foil covering the chips. The motherboard hosts the following chips - Qualcomm Snapdragon 765G SoC, Samsung MCP storage/memory combo chip, Snapdragon 865 5G Mobile Platform, Qualcomm WCD9385 Aqstic audio codec, Qualcomm Atheros WCN3998 Wi-Fi 6-ready chipset, and more.



Images courtesy:

IFIXIT

Website: iFixit.com

Teardown link:
<http://digit.in/OnePlusNord>