




Climate neutral battery

Lithium from German geothermal plants could supply a million electric vehicles a year from 2025. <https://digit.in/dec21-28>



Alibaba 3D Stacked Chip

Alibaba successfully develops world's first 3D Stacked In-Memory Computing Chip Based on DRAM. <https://digit.in/dec21-29>



Far from being repair-friendly

So far, the buds have been disassembled but they are not exactly repair-friendly due to soldered components. The case is a bit more troublesome to open up since the two halves of the case housing the battery is connected via clips that aren't just glued but also break pretty easily when opening. Opening the case reveals a single cell battery rated at 2.194Wh.



Nothing Ear (1)



Inside the stem

Inside the earbuds' stem, you will find the flex cable for gesture/touch control, a protective cover for the board, and the mainboard itself. Upon freeing the mainboard, you can find the Bestehnic BES2500YA Bluetooth Audio SoC, a microphone for calls, two charging contacts, and another microphone for environmental noise cancellation. With the board removed, you can also extract the battery cable assembly. Here you can find the soldered battery which runs at 3.7V with 31 mAh battery capacity.



Tiny button cell

Attached to the stem portion of the earbud is the tiny button cell that is between two soldered cables. This makes repair way more complex since it requires delicate soldering work. There's a plastic brace holding the cell that is embedded with a magnet that holds the earbuds securely inside the charging case. The stem is the next in line to be opened and it comes apart quickly with some heat and prying.



Images courtesy:

Website: iFixit.com

Teardown link: <https://digit.in/nothingear1>