

Complete Report (not including cost) Ver 4.3.5

Project: Church of the Ascension

Date: 4/11/2026 11:44:17 PM

Site and Catchment Information

Analysis: Specified Removal Efficiency

Catchment Name	Basin
Rainfall Zone	Florida Zone 4
Annual Mean Rainfall	52.00

Pre-Condition Landuse Information

Landuse	Low-Intensity Commercial: TN=1.13 TP=0.188
Area (acres)	13.05
Rational Coefficient (0-1)	0.29
Non DCIA Curve Number	56.00
DCIA Percent (0-100)	33.00
Nitrogen EMC (mg/l)	1.130
Phosphorus EMC (mg/l)	0.188
Runoff Volume (ac-ft/yr)	16.585
Groundwater N (kg/yr)	0.000
Groundwater P (kg/yr)	0.000
Nitrogen Loading (kg/yr)	23.108
Phosphorus Loading (kg/yr)	3.844

Post-Condition Landuse Information

Landuse	Low-Intensity Commercial: TN=1.13 TP=0.188
Area (acres)	13.05
Rational Coefficient (0-1)	0.35
Non DCIA Curve Number	55.00
DCIA Percent (0-100)	40.00
Wet Pond Area (ac)	1.24
Nitrogen EMC (mg/l)	1.130
Phosphorus EMC (mg/l)	0.188
Runoff Volume (ac-ft/yr)	17.758
Groundwater N (kg/yr)	0.000

Groundwater P (kg/yr)	0.000
Nitrogen Loading (kg/yr)	24.742
Phosphorus Loading (kg/yr)	4.116

Catchment Number: 1 Name: Basin

Project: Church of the Ascension

Date: 4/11/2026

Multiple BMP in Series Design Parameters

BMP in Series Number: 1

BMP Type: Greenroof

Selected Rainfall Station	Fort Meyers #3186
Greenroof Area (sf)	21,069.000
Retention Depth (in over greenroof area)	1.000
Irrigation Demand (inches/year)	0.000
Rainfall Excess - filtrate underdrain flow (in/yr)	0.000

BMP in Series Number: 2

BMP Type: Retention

Retention Depth (in)	0.976
Retention Volume (ac-ft)	0.961

BMP in Series Number: 3

BMP Type: Wet Detention

Permanent Pool Volume (ac-ft)	9.600
Permanent Pool Volume (ac-ft) for 31 days residence	1.508
Annual Residence Time (days)	197
Littoral Zone Efficiency Credit	
Wetland Efficiency Credit	

BMP in Series Number: 4

BMP Type: Stormwater Harvesting

Total Contributing Area to Harvesting (ac)	11.810
Total Area Available for Irrigation (ac)	6.580
Available Harvest Volume (ac-ft)	1.240
Harvest Rate (0.1-4.0 in/week)	0.200

Watershed Characteristics


Catchment Area (acres)	13.05
Contributing Area (acres)	11.810
Non-DCIA Curve Number	55.00
DCIA Percent	40.00

Rainfall Zone Florida Zone 4
 Rainfall (in) 52.00


Surface Water Discharge

Required TN Treatment Efficiency (%) 95
 Provided TN Treatment Efficiency (%) 97
 Required TP Treatment Efficiency (%) 95
 Provided TP Treatment Efficiency (%) 99

Load for Multiple BMP in Series



Load Diagram for Multiple BMP (As Used In Routing)



Summary Treatment Report Version: 4.3.5

Project: Church of the Ascension

Analysis Type: Specified Removal

Date:4/11/2026

Efficiency

BMP Types:**Routing Summary**

Catchment 1 - (Basin) Multiple BMP Catchment 1 Routed to Outlet
 Based on % removal values to the
 nearest percent

Total nitrogen target removal met? **Yes**Total phosphorus target removal met? **Yes**

Summary Report

Nitrogen

Surface Water Discharge

Total N pre load	23.11 kg/yr	
Total N post load	24.74 kg/yr	
Target N load reduction	95 %	
Target N discharge load	1.24 kg/yr	
Percent N load reduction	97 %	
Provided N discharge load	.68 kg/yr	1.5 lb/yr
Provided N load removed	24.06 kg/yr	53.06 lb/yr

Phosphorus

Surface Water Discharge

Total P pre load	3.844 kg/yr	
Total P post load	4.116 kg/yr	
Target P load reduction	95 %	
Target P discharge load	.206 kg/yr	
Percent P load reduction	99 %	
Provided P discharge load	.053 kg/yr	.12 lb/yr
Provided P load removed	4.063 kg/yr	8.959 lb/yr