





Cyclic path-OOD failure analysis for thermodynamic HistoryGNO

structured J2 shared-hole J2
Eqp increment rel. L2


Cyclic history rel. L2



Yield-surface RMS



Plastic-work lower-bound violation



(f)

Failure-analysis reading

Strict path-OOD is the stress test.
Curriculum probes whether unload/reload exposure repairs reversal memory.
Cyclic-seen is an architectural upper bound, not the main generalization claim.