

# QUALITY CONTROL





**DATE : 05-01-2026**

<b>Details</b>									
<b>Box Id</b>	Producer	csg	Lot	Variety	Packing Date	Evaluation Date	Package	Label	Size
<b>30223456</b>	PRIZE PROSERVICE	103617	000241	SANTINA	11-22-25	2025-12-31	CMR5A	RED PASSION	2JD
<b>30305150</b>	PRIZE PROSERVICE	87744	000305	SANTINA	11-25-25	2025-12-31	CMG5A	GOLD	2JD
<b>30533965</b>	PRIZE PROSERVICE	165384	030157	SANTINA	12-01-25	2025-12-31	CMR5A	RED PASSION	2JD
<b>30808486</b>	PRIZE PROSERVICE	110537	020993	LAPINS	12-07-25	2025-12-31	CMR5A	RED PASSION	3JD.
<b>30824526</b>	PRIZE PROSERVICE	176402	040040	SANTINA	12-07-25	2025-12-31	CMR5AG	RED PASSION	2JD
<b>41204961</b>	PRIZE PROSERVICE	169027	000818	LAPINS	12-08-25	2025-12-31	CMR5A	RED PASSION	2JD
<b>31038315</b>	PRIZE PROSERVICE	165384	040080	LAPINS	None	2025-12-31	CMR5A	RED PASSION	2JD
<b>40895464</b>	PRIZE PROSERVICE	3128416	000567	SANTINA	12-02-25	2025-12-31	CMR5A	RED PASSION	2JD
<b>30815343</b>	PRIZE PROSERVICE	3103320	000802	LAPINS	12-07-25	2025-12-31	CMR5AG	RED PASSION	2J
<b>41169050</b>	PRIZE PROSERVICE	177842	000793	LAPINS	12-07-25	2025-12-31	CMG5A	GOLD	3JD

## QUALITY CONTROL

### **Conditions**



Box Id	Soft	Wound	Bruise	Stain	Cracking	No Stem	Pitting	Decay	Avg Brix	Open	Firmness
30305150	0 %	1 %	0 %	0 %	0 %	5 %	16 %	0 %	17.44	GOOD	GOOD



## QUALITY CONTROL

### Conditions


Box Id	Soft	Wound	Bruise	Stain	Cracking	No Stem	Pitting	Decay	Avg Brix	Open	Firmness
30815343	0 %	7 %	0 %	0 %	0 %	3 %	5 %	0 %	16.52	GOOD	GOOD



## QUALITY CONTROL

### Conditions



Box Id	Soft	Wound	Bruise	Stain	Cracking	No Stem	Pitting	Decay	Avg Brix	Open	Firmness
31038315	0 %	2 %	0 %	0 %	0 %	3 %	0 %	1 %	18.60	GOOD	GOOD



## QUALITY CONTROL

### Conditions


Box Id	Soft	Wound	Bruise	Stain	Cracking	No Stem	Pitting	Decay	Avg Brix	Open	Firmness
30223456	12 %	0 %	0 %	0 %	0 %	7 %	2 %	0 %	16.68	GOOD	FAIR



## QUALITY CONTROL

### Conditions


Box Id	Soft	Wound	Bruise	Stain	Cracking	No Stem	Pitting	Decay	Avg Brix	Open	Firmness
40895464	0 %	4 %	10 %	12 %	11 %	6 %	2 %	2 %	17.08	GOOD	GOOD



## QUALITY CONTROL

### Conditions


Box Id	Soft	Wound	Bruise	Stain	Cracking	No Stem	Pitting	Decay	Avg Brix	Open	Firmness
30824526	1 %	6 %	11 %	3 %	6 %	3 %	9 %	3 %	16.40	GOOD	GOOD



## QUALITY CONTROL

### Conditions



Box Id	Soft	Wound	Bruise	Stain	Cracking	No Stem	Pitting	Decay	Avg Brix	Open	Firmness
30808486	11 %	0 %	0 %	0 %	0 %	9 %	5 %	0 %	20.04	GOOD	FAIR



## QUALITY CONTROL

### Conditions


Box Id	Soft	Wound	Bruise	Stain	Cracking	No Stem	Pitting	Decay	Avg Brix	Open	Firmness
41204961	0 %	0 %	0 %	2 %	0 %	16 %	1 %	0 %	18.64	FAIR	GOOD



## QUALITY CONTROL

### Conditions

Box Id	Soft	Wound	Bruise	Stain	Cracking	No Stem	Pitting	Decay	Avg Brix	Open	Firmness
30305150	0 %	0 %	0 %	0 %	0 %	12 %	6 %	0 %	18.92	GOOD	GOOD



## QUALITY CONTROL

### Conditions

Box Id	Soft	Wound	Bruise	Stain	Cracking	No Stem	Pitting	Decay	Avg Brix	Open	Firmness
30533965	0 %	0 %	2 %	16 %	2 %	4 %	0 %	0 %	17.88	GOOD	GOOD


Open	Open 2	Tag	Plate
			

Split Fruit	Defects 1	Defects 2
		

## QUALITY CONTROL

### Conditions

Box Id	Soft	Wound	Bruise	Stain	Cracking	No Stem	Pitting	Decay	Avg Brix	Open	Firmness
41169050	7 %	0 %	0 %	0 %	1 %	18 %	2 %	2 %	18.16	GOOD	GOOD



## QUALITY CONTROL

## QUALITY CONTROL